



RECEIVED

2007 NOV-1 A 10:35

DEFECTS INVESTIGATION
RECALL MGMT DIV.

Polaris Industries Inc.
Product Development Center
7290 Viking Blvd E
Wyoming, MN 55092
T: 651-408-7579
F: 651-408-7605

October 30, 2007

07V-510
(5 pages)

National Highway Traffic Safety Administration
Patricia Wallace, Office of Defects Investigation
400 Seventh Street, S.W.
Washington, D.C. 20590
T: (202) 366-5232
F: (202) 366-7882

Dear Ms. Wallace:

573.6 Defect Information Report

573.6.c.1.

Vehicle manufacturer's full name:

Polaris Industries Inc., Victory Motorcycle Division

Address:

2100 Highway 55
Medina, MN 55340-9800

573.6.c.2.

Vehicles potentially containing defect:

MY 2008 Victory Vision motorcycles.

Vehicle Identification Numbers:

A list of affected VINs is attached (pages 4 and 5)

Inclusive dates of manufacture:

May 14, 2007 through October 1, 2007.

Basis for recall population:

All MY 2008 Victory Vision motorcycle models manufactured up to October 1, 2007. Machines built after October 1, 2007 have not been shipped and will be repaired prior to shipping.

573.6.c.3.

Total number of vehicles potentially containing defect:

A total of 326 vehicles may contain this defect.

573.6.c.4.

Percentage of vehicles estimated to actually contain defect:

Victory estimates that approximately 1.0 percent of the manufactured units may have this defect.

573.6.c.5.

Brief Summary:

Victory has determined that a defect may exist in the regulator/rectifier assembly which may cause an overcharging condition. An overcharging situation in conjunction with a loose battery connection could cause a stalling condition.

Detailed description:

Victory has determined that some defective regulator/rectifier assemblies were delivered to Victory by its supplier. The root cause of the issue is due to inadequate process control during the circuit board soldering process. The improper soldering can cause an internal short. The defective regulator could cause a high voltage event which will cause the check engine light to appear.

If there is a loose battery connection along with the defective regulator, the Power-Train Control Module may inaccurately process the various engine control inputs. This could lead to a stalling condition.

573.6.c.6.

Chronology:

Victory is aware of two field reports of failed regulator/rectifier assemblies, none of which resulted in a stalling issue. These failures occurred on October 5, 2007 and on October 9, 2007.

Upon becoming aware of the failed regulators, Victory stopped shipment of vehicles and began investigating the issue. This investigation revealed that a defective regulator/rectifier assembly in conjunction with a loose battery cable could cause a stalling issue.

573.6. c.8.

Remedy program:

For machines that have been shipped to its dealer network, Victory will conduct a safety recall by which we will require our dealer network to replace the voltage regulator/rectifier assembly. Victory will further instruct our dealer network to inspect the battery cable connections for proper torque.

Machines that have not been shipped out of Victory's control will be repaired prior to being shipped.

Estimated date on which notifications to Owners will begin:

November 5, 2007.

Estimated date on which notification will be completed:
November 12, 2007.

573.6.c.10.


Owner letter:

See attached Owner Notification letter.

573.6.c.11.

Manufacturer's campaign number:

V-07-01

Signed:  Date: 10-30-2007
Don L. Good
Product Compliance Specialist
Polaris Industries Inc.

VINs	VINs	VINs	VINs
5VPSD36D683008429	5VPSD36D383002216	5VPSB36D583001249	5VPSD36D883002079
5VPSD36L283008435	5VPSD36D083001928	5VPSB36D583000683	5VPSB36D483001002
5VPS236D283008465	5VPSD36D183002408	5VPSB36D783000622	5VPSD36D583001598
5VPSB36D183000163	5VPSD36D083001931	5VPSB36D583001221	5VPSB36D783000703
5VPSB36D583000117	5VPSD36D883001661	5VPSD36D483001592	5VPSB36D883001133
5VPSB36D583000120	5VPSD36D683002291	5VPSB36D983001173	5VPSB36D383001105
5VPSB36D283000138	5VPSD36D383001969	5VPSB36D983000220	5VPSD36D483001883
5VPS136D483000144	5VPSD36L783002047	5VPSD36D183001565	5VPSD36D283001512
5VPSD36D083001685	5VPSD36D583001682	5VPSB36D783001012	5VPSD36D583002489
5VPSD36D683001349	5VPSB36L183001269	5VPSD36D683001285	5VPSB36D483000187
5VPSD36D383001907	5VPSB36L483001492	5VPSB36D083000882	5VPSB36D683000921
5VPSB36D283001189	5VPSB36D883002380	5VPSD36D583002279	5VPSB36D483001193
5VPSD36D583001293	5VPSD36D783001943	5VPSB36D283000172	5VPSB36D083000235
5VPSD36D983001989	5VPSD36D583001794	5VPSD36D983001703	5VPSD36DX83002228
5VPSD36D383002023	5VPSD36D583002332	5VPSD36DX83001550	5VPSD36L283001436
5VPSD36D583001634	5VPSD36L483001440	5VPSB36DX83000954	5VPSB36D783001169
5VPSD36D583001679	5VPSD36D283001977	5VPSB36D883001228	5VPSB36D483000612
5VPSB36D383000214	5VPSB36LX83001500	5VPSB36D583001185	5VPSD36D183002019
5VPSD36D983001913	5VPSD36D883002132	5VPSB36D583002353	5VPSD36DX83001452
5VPSB36D883000984	5VPSD36DX83001953	5VPSD36D983002303	5VPSD36D783001652
5VPSD36D383001700	5VPSD36D483002001	5VPSD36D583001763	5VPSB36D883000208
5VPSD36D783001392	5VPSD36D783001523	5VPSD36D983002091	5VPSB36L983001424
5VPSD36D883001384	5VPSD36D183001341	5VPSD36D783001277	5VPSB36DX83000632
5VPSD36D683001321	5VPSD36D083001380	5VPSD36DX83001760	5VPSD36D183001775
5VPSD36DX83001631	5VPSD36D883002258	5VPSB36D383000147	5VPSB36D383000178
5VPSB36D683001017	5VPSD36D983001748	5VPSD36D683001965	5VPSD36D583002136
5VPSB36D983000699	5VPSD36D183001940	5VPSB36D483001209	5VPSB36D783000166
5VPSD36DX83001368	5VPSD36LX83001622	5VPSD36D683001769	5VPSD36D883001305
5VPSD36D683001772	5VPSB36D383000181	5VPSB36D783002399	5VPSB36D683000160
5VPSD36D983001281	5VPSD36D983002513	5VPSB36D783001141	5VPSD36D483001317
5VPSD36L383001428	5VPSD36D983002544	5VPSD36D383002300	5VPSD36D283002112
5VPSD36D983001412	5VPSD36LX83002043	5VPSB36DX83000890	5VPSD36D283001333
5VPSB36D583000943	5VPSD36D883001742	5VPSD36DX83001709	5VPSD36D183002201
5VPSD36DX83001404	5VPSB36L683002210	5VPSD36D883001949	5VPSD36D683001559
5VPSD36D283001400	5VPSD36D383001664	5VPSB36D383000911	5VPSB36D183000695
5VPSD36D983002396	5VPSD36D983001376	5VPSB36D483001257	5VPSB36D983002386
5VPSD36D783001408	5VPSB36D183001233	5VPSB36D383001556	5VPSD36D183001601
5VPSD36D483002273	5VPSB36D983000878	5VPSD36D983002124	5VPSB36D683000126
5VPSD36D283001610	5VPSB36L383001273	5VPSD36DX83001922	5VPSB36D683000157
5VPSD36D283001297	5VPSD36D383002264	5VPSD36D583001309	5VPSD36D983001345
5VPSD36D283001655	5VPSD36D183002120	5VPSD36D583001553	5VPSB36D983000671
5VPSD36D683002288	5VPSD36D483001916	5VPSB36D483000691	5VPSD36D083001640
5VPSD36D083002402	5VPSD36DX83001676	5VPSD36D683001688	5VPSD36D983001751
5VPSD36D183002411	5VPSB36D783001253	5VPSD36D883001613	5VPSD36D483001544
5VPSB36DX83001604	5VPSB36D583000649	5VPSB36D483000948	5VPSD36D983001961

5VPSD36D883001658	5VPSD36D683001934	5VPSB36D783000894	5VPSD36D983001460
5VPSB36D483002392	5VPSD36D583002329	5VPSB36D783000202	5VPSD36D783001456
5VPSD36D283002031	5VPSB36D183000129	5VPSB36D683000997	5VPSB36D683000966
5VPSD36D283001803	5VPSB36D783000653	5VPSD36D583001889	5VPSD36D883002051
5VPSD36D683002341	5VPSD36D183002246	5VPSB36D283000902	5VPSD36D483002225
5VPSB36D683001177	5VPSD36D883001997	5VPSD36D583001892	5VPSD36D483002368
5VPSD36D383001535	5VPSD36D483002435	5VPSB36D483000898	5VPSB36D083001241
5VPSD36D683002243	5VPSD36D583002198	5VPSD36D983002107	5VPSD36D083001301
5VPSD36D283001784	5VPSD36D583002055	5VPSB36D483000707	5VPSD36D783002297
5VPSD36D683002095	5VPSD36D883001904	5VPSD36DX83002116	5VPSB36DX83001165
5VPSD36D483001673	5VPSB36D283001547	5VPSD36D883001577	5VPSD36D783001733
5VPSD36D283002417	5VPSD36D083002335	5VPSB36D783000636	5VPSD36D783001568
5VPSD36D983002267	5VPSD36L483001910	5VPSB36D983001237	5VPSB36DX83002347
5VPSD36DX83001919	5VPSD36L383001364	5VPSD36D783002087	5VPSD36D183002103
5VPSD36D283001946	5VPSB36D883000886	5VPSD36D483001981	5VPSD36D783002039
5VPSD36D183002389	5VPSD36D183001730	5VPSB36D683001213	5VPSD36D983002222
5VPSB36D483001145	5VPSD36D383001583	5VPSD36D383002099	5VPSD36D883001806
5VPSD36DX83002035	5VPSD36D883001580	5VPSD36D883002423	5VPSD36D683001562
5VPSD36D983001880	5VPSB36D283000205	5VPSB36D583001137	5VPSB36D383000861
5VPSD36D783001800	5VPSB36DX83000906	5VPSD36D783002249	5VPSD36D583002282
5VPSD36D283001736	5VPSB36D283000687	5VPSD36D583001925	5VPSB36D183001149
5VPSD36D883001739	5VPSB36D183000972	5VPSD36D483001589	5VPSD36D983001541
5VPSD36D383002426	5VPSB36D383001153	5VPSB36D283001225	5VPSB36DX83000226
5VPSB36D383001217	5VPSD36D383002071	5VPSB36D383000617	5VPSB36L083002252
5VPSD36D083001993	5VPSD36D483001706	5VPSD36D083002075	5VPSB36L583002148
5VPSD36D383001745	5VPSD36D783001313	5VPSD36D083001766	5VPSD36D783001649
5VPSD36L183001444	5VPSB36D683001129	5VPSD36D883001448	5VPSB36D883000175
5VPSD36D983001667	5VPSD36D983001877	5VPSD36D983002270	5VPSD36D283001607
5VPSB36D883001245	5VPSB36D883001021	5VPSD36D783001571	5VPSD36D883002261
5VPSD36D583001973	5VPSD36D783002414	5VPSB36D383000679	5VPSB36D783000667
5VPSD36D683002338	5VPSB36D283001161	5VPSD36D183001646	5VPSD36L583001432
5VPSD36D083002383	5VPSB36D483000657	5VPSD36D483001396	5VPSB36D183000597
5VPSB36D283000916	5VPSB36D083002356	5VPSD36D583001388	5VPSD36DX83001595
5VPSD36D683002128	5VPSD36D983001586	5VPSB36D583000960	5VPSD36D183001372
5VPSB36D783000135	5VPSD36D183001937	5VPSD36D783001778	5VPSD36D683001643
5VPSD36DX83001791	5VPSD36D383001874	5VPSB36D283000866	5VPSD36D283002059
5VPSD36DX83001337	5VPSD36D183002067		

SUBJECT: Recall Campaign - Voltage Regulator / Battery
2008 Victory Vision™ Street and Victory Vision™ Tour models
Warning and Safety Recall Notice 07V-xxx (07-xxx in Canada)
Reference: Victory Safety Recall Bulletin V-07-01
PLEASE READ IMMEDIATELY

October 30, 2007

Dear Victory Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. The Victory Motorcycle Division of Polaris Industries Inc. has decided that a defect which relates to motor vehicle safety exists in some model year 2008 Victory Vision motorcycles. Our records indicate that you have purchased a potentially affected vehicle.

The reason for this recall:

Victory has determined that a defect may exist in the regulator/rectifier assembly which may cause an overcharging condition. An overcharging situation in conjunction with a loose battery cable connection could cause the engine to stall. An unexpected loss of engine power increases the risk of a loss of control and a vehicle crash.

What Victory and your dealer will do:

Victory has issued Safety Recall Bulletin V-07-01 to all Victory dealers, with instructions to replace the voltage regulator / rectifier and verify both battery cables are properly tightened on all affected vehicles. Repairs will be made by any authorized Victory motorcycle dealer at no cost to you. The actual repair will take approximately one hour to perform; however, it may take longer due to service scheduling requirements.

What you should do:

Please call your authorized Victory motorcycle dealer to schedule an appointment to have the bulletin repair performed.

If you have questions or if you need more information:

While your Victory dealer is in the best position to answer your questions, if you have any questions that your dealer cannot address, or if you are having difficulty obtaining the recall repair outlined in this letter, or if you no longer own the affected motorcycle, please contact our Victory Consumer Service Department using the contact information listed below.

If you believe that the Victory Motorcycle Division of Polaris Industries Inc. has failed to remedy this defect without charge or is unable to do so within a reasonable time, you may submit a complaint to the Administrator of the National Highway Traffic Safety Administration, 400 Seventh Street S.W., Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-424-9153); or go to <http://www.safercar.gov>.

Please accept our apologies for any inconvenience this may cause you. Your safety and continued satisfaction with your Victory motorcycle is our primary concern. Thank you for your prompt attention to this matter.

Sincerely,
Polaris Industries Inc.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days. If you are no longer the owner of the Victory motorcycle indicated by this letter, please contact any authorized Victory dealer

Polaris Industries Inc.
Consumer Service Department
2100 Highway 55
Telephone: (888) 704-5290