

Safety Defect and Noncompliance Report Guide for Vehicles
PART 573 Defect and Noncompliance Responsibility and Reports¹

07V-560
(6 pages)

On November 26, 2007, Weekend Warrior Trailers, Inc [MFR] decided that (a defect which relates to motor vehicle safety)(a noncompliance with Federal Motor Vehicle Safety Standard No. _____) exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Responsibility and Reports.

Date this report was prepared: November 26, 2007

Furnish the manufacturer's identification code for this recall (if applicable):06E-016

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

Weekend Warrior Trailers, Inc

1320 Oleander Ave.

Perris, CA 92571

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.

Bryan Atkinson

Service Director


Telephone Number: 909-579-0353 _____ Fax No.: 909-579-0376 _____

Name and Title of Person who prepared this report.

Bryan Atkinson

Director of Service

Signed:



RECEIVED

2007 DEC-12 A 10:35

DEFECTS INVESTIGATION
RECALL MGMT DIV.

¹ Each manufacturer must furnish a report, to the Associate Administrator for Enforcement, for each defect or noncompliance condition which relates to motor vehicle safety.

This guide was developed from 49 CFR Part 573, "Defect and Noncompliance Responsibility and Reports" and also outlines information currently requested. Any questions, please consult the complete Part 573 or contact Mr. George Person at (202) 366-5210, by FAX at (202) 366-7882, or by E-Mail to RMD.ODI@dot.gov.

I. Identify the Vehicle Models Involved in the Recall

2. Identify the Vehicles Involved in the Recall, for each make and model or applicable vehicle line (provide illustrations or photographs as necessary to describe the vehicle), provide:

Make(s): Weekend Warrior **Model Years Involved:** 2007 **Model(s):** FB, CL, FSC, FS, LE, CR

Production Dates: Beginning: January 18, 2006 **Ending:** February 9, 2006

VIN Range: Beginning: 5HRFF26267C016422 **Ending:** 5HRFF28277X016541

VIN Range: Beginning: 5HRFF23257C016738 **Ending:** 5HRFF25207C016823

VIN Range: Beginning: 5HRSS353X7C016868 **Ending:** 5HRSS39337C016950

Vehicle Type: Recreational Vehicle **Bodystyle:** Toy-Hauler

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

There are no descriptive differences between affected vehicles and those not included.

Make(s): _____ **Model Years Involved:** _____ **Model(s):** _____

Production Dates: Beginning: _____ **Ending:** _____

VIN Range: Beginning: _____ **Ending:** _____

Vehicle Type: _____ **Bodystyle:** _____

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Make(s): _____ **Model Years Involved:** _____ **Model(s):** _____

Production Dates: Beginning: _____ **Ending:** _____

VIN Range: Beginning: _____ **Ending:** _____

Vehicle Type: _____ **Bodystyle:** _____

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents. For example, if the recall involved Vehicles equipped with certain items of equipment from January 1, 1996 through April 1, 1997, then what was the percentage of the recalled Vehicles of all Vehicles manufactured during that time period.

II. Identify the Recall Population

3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

Model	Year	Number of Vehicles Potentially Involved
FB2600	2007	9
FB2200	2007	32
CL4005	2007	20
FSC3200	2007	30
FSC2800	2007	29
FS2300	2007	65
FS2500	2007	21
LE3505	2007	18
LE3305	2007	18
LE3105	2007	18
CR3705	2007	19
CR3905	2007	10

Total Number Potentially Affected by the Recall:

289

4. Furnish the approximate percentage of the total number of vehicles estimated to actually contain the defect or noncompliance:

Identify and describe how the recall population was determined—in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled vehicles:

Great Plains Industries Inc. manufactured possibly defective pumps between August 2005 and February 2006. Weekend Warrior Trailers, Inc. started utilizing GPI pumps on January 18, 2006.

Between the start of using GPI fuel pumps and the notification by GPI that there were possibly defective pumps in Weekend Warrior Trailers, Inc.'s stock, a total of 289 fuel pumps had already been installed. GPI sent representatives out to Weekend Warrior Trailers, Inc. to change all pumps Out; 289 installed pumps were replaced and approximately 200 uninstalled pumps were Replaced.

III. Describe the Defect or Noncompliance

5. Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

A fuel leak at the inlet (suction, low pressure) side of fuel pump

Describe the cause(s) of the defect or noncompliance condition.

An inlet fitting is installed into the inlet of the pump. The fitting is sealed and secured by an

Epoxy adhesive. Insufficient epoxy adhesive was applied at the time of installation at the factory.

Describe the consequence(s) of the defect or noncompliance condition.

Pump installation varies by OEM. If the pump is installed above the supply tank with a check

Valve (backflow preventer or roll-over protection valve) in the suction line or if the pump is

Installed below the supply tank, the defect can cause a low pressure leak at the pump inlet.

Identify any warning which can (a) precede or (b) occur.

Visible fuel leak

If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

Great Plains Industries, Inc.

5252 East 36th Street North

Wichita, Kansas 67220

Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:

Bob Calvert, Chief Engineer

IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

Friday, January 20, 2006. GPI receives call from OEM about two leaking pumps.

Monday, January 21, 2006. GPI had personel at OEM to identify the problem and began rework
And replacement of pumps at that location.

Friday, January 27, 2006. GPI understood the scope of the problem and began to address with
All OEM customers. (taken from GPI's 573 report)

- Mid-February, GPI representatives replaced all installed and uninstalled pumps at all
Weekend Warrior Trailers, Inc.'s locations. No units left the Weekend Warrior Trailers, Inc
Facility with the possibly defective fuel pumps installed.

V. Identify the Remedy

8. A description of the manufacturer's program for remedying the defect or noncompliance. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of the manufacturer's notification of owners, purchasers and dealers, in accordance with §573.13 of this part. A manufacturer's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by §573.13 that is not in a general reimbursement plan shall be submitted in the manufacturer's report to NHTSA under this section. If a manufacturer submits one or more general reimbursement plans, the manufacturer shall update each plan every two years, in accordance with §573.13. The manufacturer's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters.

N/A

9. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

GPI will replace the ump at no cost to the OEM or user. Weekend Warrior Trailers, Inc does
Not have any possibly affected products needing replacement.

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

N/A

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

"see GPI's 573 report"

VI. Identify the Recall Schedule

10. Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

N/A

VII. Furnish Recall Communications

11. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification. *A DRAFT copy of the notification documents should be submitted to this office by Fax (202-366-7882) or by E-Mail to RMD.ODI@dot.gov for review prior to mailing.*

Note that these documents are to be submitted separately from those provided in accordance with Part 579.5 requirements.