

AIRTEX PRODUCTS, LP

AIRTEX AUTOMOTIVE DIVISION

SAFETY RECALL - BULLETIN FP072007-1

October 22, 2007

To: Vehicle Owner

Subject: FUEL PUMP SAFETY RECALL FP072007-1

Part Number: E7081H Fuel Pump Module

Vehicle Applications:	1999-1995	Chrysler Sebring 2.0L, exc. Conv.
	2000-1995	Chrysler Sebring 2.5L, exc. Conv.
	1999-1995	Dodge Avenger 2.0 L
	2000-1995	Dodge Avenger 2.5L
	1998-1995	Eagle Talon 2.0L non-turbo
	1999-1995	Mitsubishi Eclipse, Eclipse Spyder 2.0L, non-turbo
	1996	Mitsubishi Eclipse, Eclipse Spyder 2.4L
	1998-1994	Mitsubishi Galant 2.4L, exc. California

This notice is being sent to you under the requirements of the National Traffic Motor Vehicle Safety Act. Airtex has decided that a defect which relates to motor vehicle safety exists in certain Airtex fuel pump modules that may have been installed on your vehicle.

You have been identified as the possible purchaser/installer of an effected Airtex or Master brand fuel pump module sold/installed between May 7, 2007 and July 19, 2007. The defect, which is described below, may not exist in every Airtex or Master brand fuel pump module E7081H sold between May 7, 2007 and July 19, 2007. Nevertheless, please review the following information carefully and follow all applicable instructions. If you have any questions about this recall, please notify Airtex Customer Service at 1-800-880-3056. If you no longer own the vehicle on which the fuel pump module was installed, please notify Airtex and, if possible, identify the current or last-known owner.

The cause of the potential failure associated with this defect may prevent the mating threaded fittings from bottoming out before an adequate seal is achieved. This condition may result in leakage of fuel at the connection of the vehicle fuel line and the fuel pump module assembly. In the presence of an ignition source, a fuel leak could result in a fire. As of the date of this letter Airtex has initiated a program to replace fuel pump modules that may be affected by this defect, at no charge to the owner. Please complete the following instructions to determine whether you should take advantage of this program.

NOTE: IF YOU HAVE ANY QUESTIONS REGARDING THESE INSTRUCTIONS, CANNOT COMPLETE THEM, OR ARE UNCERTAIN AS TO HOW TO PROCEED, PLEASE CALL AIRTEX CUSTOMER SERVICE AT 1-800-880-3056 FOR ASSISTANCE.

If an affected fuel pump module was installed on your vehicle during the dates listed, the unit must be inspected and, if suspect, must be replaced. Immediately call Airtex Customer Service 1-800-880-3056 to have the module inspected.

407 West Main Street
Fairfield, IL 62837
800.880.3056
www.airtexproducts.com

A I R T E X P R O D U C T S , L P

AIRTEX AUTOMOTIVE DIVISION

You will be instructed to take your vehicle to a qualified technician to have the affected fuel pump module inspected or replaced. Inspection of the fuel pump and subsequent replacement will be done without charge to you.

If a replacement pump is required a module will be shipped directly to your attention. A check for reimbursement will be mailed to your attention upon our receipt of the recalled unit and an invoice documenting the cost of the replacement.

If you have had your vehicle repaired prior to receipt of this notice, you may be entitled to reimbursement if you incurred any out of pocket cost due to this matter. For further information, please contact us at 1-800-880-3056.

On the form enclosed please enter the required information. Once the unit has been replaced, return the completed form, the Installer's invoice for replacement and the recalled unit to:

Airtex Products
Product Safety Bulletin FP072007-1
407 West Main Street
Fairfield, IL 62837

If you have purchased and not yet installed the affected fuel pump module please return the unit to Airtex for a free replacement fuel pump module. Please include a completed copy of the enclosed form and a valid receipt.

Make reference to **FUEL PUMP SAFETY RECALL FP072007-1** in all your correspondence, packing and shipping documents.

If you have any questions concerning this safety related recall, please contact us by calling Customer Service at 1-800-880-3056. After contacting your installer or Airtex, if you are still not able to have the safety defect remedied without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, D.C. 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Please accept our apology for any inconvenience incurred as a result of this issue. We are taking this action in the interest of your safety and continued satisfaction with our products. Thank you for your attention and cooperation to this very important matter.

Very truly yours,

Pam Schell
Customer Service Manager

FP072007-1VO

407 West Main Street
Fairfield, IL 62837
800.880.3056
www.airtexproducts.com

A I R T E X P R O D U C T S , L P

AIRTEX AUTOMOTIVE DIVISION

Product safety Bulletin FP072007-1

Date: _____ *Reference Number: _____

Vehicle Owner Name: _____

Address: _____

City/State/Zip code: _____

Phone Number: _____

Vehicle, Year, Make, Model: _____

VIN: _____

Fuel Pump Part Number: _____

Date Originally Installed: _____

Date Replacement Installed: _____

Replacement Cost: _____

Installer Name: _____

Company Name: _____

Address: _____

City/State/Zip code: _____

Phone Number: _____

Please return the recalled fuel pump module, completed copy of this form and the Installer's invoice documenting replacement to:

Airtex Products
Product Safety Bulletin FP072007-1
407 West Main Street
Fairfield, IL 62837

customerservice@airtexproducts.com

1-800-880-3056

Fax: 1-618-842-4069

* To be assigned by Airtex

TechLine: 1-800-424-7839

407 West Main Street
Fairfield, IL 62837
800.880.3056
www.airtexproducts.com