



# SERVICE ALERT

July 31, 2007

SA07RE-01

NAS:

US Only:

Cda Only:

**ATTENTION:** Centre Manager, Sales Manager,  
Service Manager, Service Advisor, Technician  
Parts Manager, Warranty Admin

## Freelander Brake Light Switch Safety Recall

### RECALL P004 Replaces RECALL P002

Land Rover has identified a concern with the brake light switch on 2002 to 2005 model year Freelander vehicles in North America. The brake lights may remain illuminated even when the brake pedal is not depressed. Improperly functioning brake lights could result in the vehicle being involved in a crash.

Recall **P002** previously announced this issue and directed that an inspection of brake light function was to be undertaken. If indicated by the inspection, a new brake light switch of the existing specification was to be temporarily installed.

Publication of the **P004** Recall bulletins listed below terminates the P002 campaign and replaces it with a process to install a new-specification brake light switch on all affected vehicles (including any that were temporarily repaired under P002).

**NOTE: Check the disposition of any vehicle using Direct Dealer Warranty (DDW) "Vehicle Inquiry" screen. All affected vehicles currently held in Retailer inventory as new or used vehicles must be repaired prior to sale.**

See the bulletins listed below posted on GTR and the InfoTrail Internet sites for detailed descriptions of the Recall. Owner notification will begin during the week of 30 July 2007.

- **Technical Information Bulletin found on GTR**  
P004 – RECALL: Brake Light Switch
- **Service Bulletins found on Land Rover InfoTrail**  
SRE07-05 - SAFETY RECALL P004 – (NHTSA # 07V-041) (TC # 07-031).

**NOTE: All retailer personnel should familiarize themselves with the content of these bulletins as they relate to their contact with customers and with their job activities.**

The availability of the latest configuration brake light switch means that the inspection and potential repair procedure published in Technical Bulletin P002 is no longer to be used. **All recall-related repairs must be made using the new-specification brake light switch XKB500120 and the associated link lead YMQ503280.**

The Bulletins SRE07-01, SRE07-04 and SRE07-04C relating to Recall P002 will be withdrawn from InfoTrail. Technical Bulletin P004 will replace P002 on GTR.

**Effective immediately, ALL vehicles should be repaired in accordance with the parts and repair procedures in Technical Bulletin P004. All claims for the repairs previously performed under P002 must be submitted for processing before the close of business on 8 August 2007. All Option Codes for Recall Campaign P002 will be closed for claim submission after that date.**