



Frank M. Ligon  
Director  
Service Engineering Operations  
Ford Customer Service Division

Ford Motor Company  
P. O. Box 1904  
Dearborn, Michigan 48121

March 2, 2007

**INFORMATION ONLY**

**TO:** All U.S. Ford and Lincoln Mercury Dealers

**SUBJECT:** Awareness Communication: Upcoming Safety Recall 07S48  
Certain 2003 through 2005 Model Year Crown Victoria Police Interceptor (CVPI) Vehicles -  
16" Steel Wheel Replacement

**REASON FOR THIS COMMUNICATION**

To inform you that Ford Motor Company is notifying the National Highway Traffic Safety Administration (NHTSA) of an upcoming safety recall on the affected vehicles. Once NHTSA has been informed, there is a possibility that you may be contacted by customers about the recall. This notice will help you answer customer questions.

**REASON FOR THIS SAFETY RECALL**

Some police fleets have reported instances of slow tire air loss due to a cracked 16" steel road wheel.

**AFFECTED VEHICLES**

This program covers all 2003 through 2005 Crown Victoria Police Interceptor (CVPI) vehicles (body code P71) built at the St. Thomas Assembly Plant from October 10, 2001 through December 8, 2004 that are currently in active law enforcement duty that may be likely to encounter high speed pursuit driving.

**SERVICE ACTION**

It is anticipated that a complete Dealer Bulletin will be provided to Dealers the week of March 5, 2007. The bulletin will provide parts ordering information and repair instructions.

**CUSTOMER NOTIFICATION**

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

**OASIS AND FSA VIN LISTS**

OASIS will be activated and FSA VIN listings will be available when the Dealer Bulletin is published.

**QUESTIONS?**

Special Service Support Center (Dealer Only) Questions:..... 1-800-325-5621