



A Subsidiary of **FREIGHTLINER**
CORPORATION

Product Recall

To: ALL DEALERS

From: TRACY SAUERBREY – WARRANTY/RECALL DEPARTMENT

Subject: RECALL 07V-137 – Brake Pedal Interference

Date: February 20, 2008


Enclosed are copies of the customer notification letter and the repair procedure for Recall 07V-137. This recall involves certain HDX and MVP-ER units manufactured between January 1, 1995 and November 14, 2003. The defect involves the service air brake pedal, for both non-adjustable and adjustable brake pedals. The service air brake may contact the front structure on certain school buses, limiting the maximum brake force available.

This is a universal notification sent to all dealers. You may or may not have customers in your area affected by this recall. If owners in your area are subject to this recall, we have enclosed a printout listing those customers' names and addresses. If there is not a printout enclosed according to our records there are no units in your area involved. **If you have a printout and any of the units on it are still in your possession it is your responsibility to ensure the recall is performed before the unit is delivered to the customer.**

The repair will consist of replacing the pedal push rod. The labor allowance is .7 hour per unit. (SRT code 90-74). You will need to order kit number TBB 85490080 from the Parts Distribution Center.

Thomas Built Buses has elected to notify all customers directly. Your customers will be contacting you to schedule an appointment for repairs. Reimbursement for parts and labor, (if requested) may be obtained by filing a warranty claim.

If you know of any customers who own or operate a Thomas bus in this recall, whose name and address is NOT listed or is INCORRECTLY listed on the enclosed printout, please promptly notify Thomas Built Buses of that additional information in writing. Thank you for your cooperation and assistance.



Tracy

Enclosures: Customer Letter Repair Procedure Printout (if applicable)