

GM SERVICE AND PARTS OPERATIONS  
DCS1830  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 9, 2007

Subject: Upcoming Product Safety Recall 06230  
Fuel Tank Inlet Check Valve

Models: 2001-2004 Pontiac Montana and Aztek  
2002-04 Chevrolet Venture  
2002-04 Buick Rendezvous

To: All Chevrolet, Pontiac and Buick Dealers

Attention: Dealer Operator, General Manager, Sales Manager, Service Manager,  
Used Car Manager, Parts Manager and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) website, the media may report that General Motors will be announcing a Product Safety recall involving certain 2001-2004 Pontiac Montana and Aztek; 2002-2004 Chevrolet Venture and Buick Rendezvous vehicles.

General Motors has decided a defect, which relates to motor vehicle safety, exists in 2001-2004 Pontiac Montana and Aztek; 2002-2004 Chevrolet Venture and Buick Rendezvous vehicles. The vehicle population is Rendezvous and Aztek vehicles built in May 2003, Venture and Montana vehicles built in June through August 2002 and all vehicles registered in Nevada, Arizona, Virgin Islands, Puerto Rico and Hawaii. Variations in the manufacturing process or exposure to high ambient temperatures may lead to fracture of the fuel tank inlet check valve (ICV) on some of these vehicles. A fracture may allow fuel vapors to pass through and allow droplets of fuel to accumulate on the side of the fuel tank.

To correct this condition, dealers will replace the fuel tank.

A total of 20,594 vehicles are involved. Dealers will be notified when customer notification letters are scheduled to be mailed.

GM Vehicle Inquiry System (GMVIS) information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE  
GM SERVICE AND PARTS OPERATIONS