

**GM SERVICE AND PARTS OPERATIONS
DCS1833
URGENT - DISTRIBUTE IMMEDIATELY**

Date: August 22, 2007

Subject: Upcoming Safety Recall 07221
ABS Wheel Speed Sensor

Models: 2008 Hummer H2 Utility and SUT

To: All Hummer Dealers

Attention: Dealer Operator, General Manager, Sales Manager,
Service Manager, Used Car Manager, Parts Manager
and Warranty Administrator

Based on information from the National Highway Traffic Safety Administration (NHTSA) website, the media may report that General Motors will be announcing a safety recall involving certain 2008 Hummer H2 Utility and SUT vehicles.

Certain wires in the Antilock Brake System (ABS) wheel speed sensor front or rear harness may be reversed. This condition could result in increased stopping distance under certain circumstances. Additionally, increased steering input could be required to maintain vehicle direction.

To correct this condition, dealers are to correct the ABS wheel speed sensor wiring, if necessary and reprogram the brake control module.

A total of 363 vehicles are involved. Dealers will be notified when customer notification letters are scheduled to be mailed.

GM Vehicle Inquiry System (GMVIS) information for this recall will not be available until the recall bulletin is released to dealers.

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS