

Number 07V11 Vendor FSA Notice	2008 F-650 and F-750 Trucks With Certain Caterpillar C7 and C9 Diesel Engines Fuel Pump Replacement
Date: September 27, 2007	

INFORMATION ONLY

This Is a Vendor Field Service Action Notice

Model Year	Model	Assembly Plant	Vehicle Build Date Range
2008	F-650 and F-750 trucks with certain Caterpillar C7 and C9 diesel engines	ESCOBEDO (MEXICO)	Certain vehicles built from April 23, 2007 through August 23, 2007

Issue

On the affected trucks, the fuel pump may leak internally, diluting the engine oil with fuel, which may cause the turbocharger to fail. This condition can result in a loss of throttle control and excessive smoke, both of which may result in a situation where a vehicle crash could occur.

Action

1. Caterpillar Inc. warrants the replacement of the fuel pump mentioned above and is conducting a Safety Recall Program to inspect and, if necessary, replace the fuel pump in affected trucks.
2. Caterpillar Inc. has contacted all authorized Caterpillar Service Centers (including Caterpillar authorized Ford dealers) and is providing parts, technical instructions, and claiming instructions for the replacement of the affected fuel pump. This notification is for your information only; this is a Caterpillar action and Ford has no administrative responsibilities for this Caterpillar action. **DO NOT SUBMIT WARRANTY CLAIMS TO FORD MOTOR COMPANY.**
3. Caterpillar Inc. has also sent all affected owners a letter asking them to have the fuel pump inspected and if necessary, replaced by an authorized Caterpillar Service Center.

Affected vehicles are identified in OASIS.

Questions?	Caterpillar Call Center: 1-800-447-4986
-------------------	---