



November 27, 2007

Dear Honda Motorcycle Dealer:

SERVICE ACTION NOTICE

AFFECTED UNITS: All 2006-2007 CBR1000RR Motorcycles

American Honda is conducting a **SERVICE ACTION** on affected models per the description above. The action will correct a problem that may exist in the brazed portion of the air vent pipe in the bottom of the fuel tank of 2006-2007 CBR1000RR motorcycles. In limited circumstances cracking could occur due to fatigue, resulting in fuel leakage.

Effective immediately **YOU MUST NOT SELL** any affected model in your inventory until the required repair has been completed. Please make sure ALL DEPARTMENTS in your dealership – Parts, Sales, and Service – are made aware of this action.

The instructions, procedures, and parts necessary to repair affected motorcycles will be made available to your dealership as soon as possible. Date specific information as to each of these items will be sent to you the week of December 10, 2007.

If you have recently sold an affected model, please submit the warranty registration information. If you have any further questions, please contact either American Honda's Techline or your District Service Manager.

Thank you for your cooperation.
American Honda Motor Co., Inc.

Robert E. Clever
Senior Manager – Service
Motorcycle Division

Dealer Bulletin	Page		Pages	File behind Dealer Guide Bulletin Tab
07-0772	1	of	1	SERVICE