



MITSUBISHI FUSO
TRUCK OF AMERICA, Inc.

2015 Center Square Road
Logan Township, NJ 08085
(856) 467-4500
(856) 467-4695 Fax

August 13, 2007

CUSTOMER
STREET
CITY, STATE ZIP

IMPORTANT!

- ❖ Please be advised that your 2001-2006 Model Year FE640, FE83D, FE84D, FE85D, FG84D or FH210 truck referenced by VIN below is open for a safety recall related to the idler gear shaft flange.
- ❖ MFTA urges that you schedule an appointment with an Authorized Dealer or Parts and Service Center to perform the recall, at no charge to you, as soon as possible.
- ❖ Refer to this Recall Notification letter when speaking with Dealer Service Department personnel.

SAFETY RECALL NOTIFICATION – C1002210 – 4M50 Idler Gear Shaft Flange
NHTSA SAFETY RECALL – 07V-138

Vehicle Identification Number – VIN

Dear Mitsubishi Fuso Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mitsubishi Fuso Truck of America, Inc. has decided that a defect which relates to motor vehicle safety exists in the 4M50 engine idler gear bushing of the above identified trucks. On affected vehicles, the cylinder head idler gear bushing may have been improperly machined, causing excessive stress on the cylinder head idler gear shaft.

Continued on the back.

Please detach, sign & return this prepaid business reply postcard if any owner/vehicle information requires updating.



OWNER/VEHICLE INFORMATION CHANGE

If this vehicle is no longer in your possession, or the address has changed, please make any necessary changes and indicate the "REASON FOR CHANGE" in the check boxes provided. If you make changes, please sign and date, detach, and return this prepaid business reply postcard.

VIN:

Owner of Record:

Owner/Address Correction:

REASON FOR CHANGE

- | | | |
|---|---|--|
| ☐ Truck Exported | ☐ Truck Totalled | ☐ Truck Scrapped/Out of Service |
| ☐ Truck Stolen | ☐ Truck Sold | ☐ Owner Address Correction |

Signature: _____ Date: ____ / ____ / ____

IMPORTANT: Sign and date this reply, as permanent changes are not valid without your signature.

If you're searching for a Dealer or
Parts and Service Center in your area,
try the "Find a Dealer" link at:
www.mitfuso.com

Continued operation in this condition could cause the idler gear shaft flange to break and generate abnormal engine noise and/or engine oil leaks. In the worst case, the engine could stall and not restart, causing a crash without warning.

On vehicles that have accrued 15,000 miles or less, the idler gear assembly will be replaced. On vehicles that have accrued more than 15,000 miles, the inside diameter of the cylinder head idler gear bushing will be measured. The idler gear assembly will be replaced if the bushing is out of specification. The procedure will be completed at no cost to you when performed by an Authorized Dealer or Parts and Service Center. The scheduled time for performing this recall is approximately 1.5 (inspection only) to 5.0 (inspection and idler gear replacement) hours.


Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you are the lessor of the above referenced vehicle, please forward this notification immediately.

Note: If you have incurred costs to obtain a remedy for the problem addressed in this recall prior to initial notification, please present the paid invoice to an Authorized Mitsubishi Fuso Dealer or Parts and Service Center. The Dealer/Parts & Service Center will submit a warranty claim to MFTA on your behalf. Reimbursement of these costs should be expected within 30 days of warranty claim submittal.


We at MFTA regret any inconvenience this situation may cause you. However, your safety and continued satisfaction with our product are most important to us.

If your MFTA Dealer is unable to perform this procedure without charge, or within a reasonable amount of time, please contact MFTA Customer Service toll-free at 877-711-0707 for assistance. You may also contact the Administrator, National Highway Traffic Safety Administration, 400 Seventh St. SW, Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,



William P. Mohr
Director, Service Operations



BUSINESS REPLY MAIL

FIRST CLASS MAIL PERMIT NO. 26 SOUTHEASTERN, PA

POSTAGE WILL BE PAID BY ADDRESSEE

MITSUBISHI FUSO
TRUCK OF AMERICA, INC.
P.O. BOX 458
SOUTHEASTERN, PA 19399-0458

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES





MITSUBISHI FUSO
TRUCK OF AMERICA, Inc.

2015 Center Square Road
Logan Township, NJ 08085
(856) 467-4500
(856) 467-4695 Fax

August 13, 2007

CUSTOMER
STREET
CITY, STATE ZIP

IMPORTANT!

- ❖ Please be advised that your 2001-2006 Model Year FE640, FE83D, FE84D, FE85D, FG84D or FH210 truck referenced by VIN below is open for a safety recall related to the idler gear shaft flange.
- ❖ MFTA urges that you schedule an appointment with an Authorized Dealer or Parts and Service Center to perform the recall, at no charge to you, as soon as possible.
- ❖ Refer to this Recall Notification letter when speaking with Dealer Service Department personnel.

SAFETY RECALL NOTIFICATION – C1002210 – 4M50 Idler Gear Shaft Flange
NHTSA SAFETY RECALL – 07V-138

Vehicle Identification Number – VIN

Dear Mitsubishi Fuso Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mitsubishi Fuso Truck of America, Inc. has decided that a defect which relates to motor vehicle safety exists in the 4M50 engine idler gear bushing of the above identified trucks. On affected vehicles, the cylinder head idler gear bushing may have been improperly machined, causing excessive stress on the cylinder head idler gear shaft.

Continued on the back.

Please detach, sign & return this prepaid business reply postcard if any owner/vehicle information requires updating.



OWNER/VEHICLE INFORMATION CHANGE

If this vehicle is no longer in your possession, or the address has changed, please make any necessary changes and indicate the "REASON FOR CHANGE" in the check boxes provided. If you make changes, please sign and date, detach, and return this prepaid business reply postcard.

VIN:

Owner of Record:

Owner/Address Correction:

REASON FOR CHANGE

- | | | |
|---|---|--|
| ☐ Truck Exported | ☐ Truck Totalled | ☐ Truck Scrapped/Out of Service |
| ☐ Truck Stolen | ☐ Truck Sold | ☐ Owner Address Correction |

Signature: _____ Date: ____ / ____ / ____

IMPORTANT! Sign and date this reply, as permanent changes are not valid without your signature.

If you're searching for a Dealer or
Parts and Service Center in your area,
try the "Find a Dealer" link at:
www.mitfuso.com

Continued operation in this condition could cause the idler gear shaft flange to break and generate abnormal engine noise and/or engine oil leaks. In the worst case, the engine could stall and not restart, causing a crash without warning.

On vehicles that have accrued 15,000 miles or less, the idler gear assembly will be replaced. On vehicles that have accrued more than 15,000 miles, the inside diameter of the cylinder head idler gear bushing will be measured. The idler gear assembly will be replaced if the bushing is out of specification. The procedure will be completed at no cost to you when performed by an Authorized Dealer or Parts and Service Center. The scheduled time for performing this recall is approximately 3.0 (inspection only) to 7.0 (inspection and idler gear replacement) hours.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you are the lessor of the above referenced vehicle, please forward this notification immediately.

Note: If you have incurred costs to obtain a remedy for the problem addressed in this recall prior to initial notification, please present the paid invoice to an Authorized Mitsubishi Fuso Dealer or Parts and Service Center. The Dealer/Parts & Service Center will submit a warranty claim to MFTA on your behalf. Reimbursement of these costs should be expected within 30 days of warranty claim submittal.

We at MFTA regret any inconvenience this situation may cause you. However, your safety and continued satisfaction with our product are most important to us.

If your MFTA Dealer is unable to perform this procedure without charge, or within a reasonable amount of time, please contact MFTA Customer Service toll-free at 877-711-0707 for assistance. You may also contact the Administrator, National Highway Traffic Safety Administration, 400 Seventh St. SW, Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,



William P. Mohr
Director, Service Operations



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL

FIRST CLASS MAIL PERMIT NO. 26 SOUTHEASTERN, PA

POSTAGE WILL BE PAID BY ADDRESSEE

MITSUBISHI FUSO
TRUCK OF AMERICA, INC.
P.O. BOX 458
SOUTHEASTERN, PA 19399-0458





MITSUBISHI FUSO
TRUCK OF AMERICA, Inc.

2015 Center Square Road
Logan Township, NJ 08085
(856) 467-4500
(856) 467-4695 Fax

August 13, 2007

CUSTOMER
STREET
CITY, STATE ZIP

IMPORTANT!

- ❖ Please be advised that your 2001-2006 Model Year FE640, FE83D, FE84D, FE85D, FG84D or FH210 truck referenced by VIN below is open for a safety recall related to the idler gear shaft flange.
- ❖ MFTA urges that you schedule an appointment with an Authorized Dealer or Parts and Service Center to perform the recall, at no charge to you, as soon as possible.
- ❖ Refer to this Recall Notification letter when speaking with Dealer Service Department personnel.

SAFETY RECALL NOTIFICATION – C1002210 – 4M50 Idler Gear Shaft Flange
NHTSA SAFETY RECALL – 07V-138

Vehicle Identification Number – VIN

Dear Mitsubishi Fuso Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mitsubishi Fuso Truck of America, Inc. has decided that a defect which relates to motor vehicle safety exists in the 4M50 engine idler gear bushing of the above identified trucks. On affected vehicles, the cylinder head idler gear bushing may have been improperly machined, causing excessive stress on the cylinder head idler gear shaft.

Continued on the back.

Please detach, sign & return this prepaid business reply postcard if any owner/vehicle information requires updating.



OWNER/VEHICLE INFORMATION CHANGE

If this vehicle is no longer in your possession, or the address has changed, please make any necessary changes and indicate the "REASON FOR CHANGE" in the check boxes provided. If you make changes, please sign and date, detach, and return this prepaid business reply postcard.

VIN:

Owner of Record:

Owner/Address Correction:

REASON FOR CHANGE

- | | | |
|---|---|--|
| ☐ Truck Exported | ☐ Truck Totalled | ☐ Truck Scrapped/Out of Service |
| ☐ Truck Stolen | ☐ Truck Sold | ☐ Owner Address Correction |

Signature: _____ Date: ____ / ____ / ____

IMPORTANT! Sign and date this reply, as permanent changes are not valid without your signature.

If you're searching for a Dealer or
Parts and Service Center in your area,
try the "Find a Dealer" link at:

www.mitfuso.com

Continued operation in this condition could cause the idler gear shaft flange to break and generate abnormal engine noise and/or engine oil leaks. In the worst case, the engine could stall and not restart, causing a crash without warning.

On vehicles that have accrued 15,000 miles or less, the idler gear assembly will be replaced. On vehicles that have accrued more than 15,000 miles, the inside diameter of the cylinder head idler gear bushing will be measured. The idler gear assembly will be replaced if the bushing is out of specification. The procedure will be completed at no cost to you when performed by an Authorized Dealer or Parts and Service Center. The scheduled time for performing this recall is approximately 10.0 (inspection only) to 15.0 (inspection and idler gear replacement) hours.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you are the lessor of the above referenced vehicle, please forward this notification immediately.

Note: If you have incurred costs to obtain a remedy for the problem addressed in this recall prior to initial notification, please present the paid invoice to an Authorized Mitsubishi Fuso Dealer or Parts and Service Center. The Dealer/Parts & Service Center will submit a warranty claim to MFTA on your behalf. Reimbursement of these costs should be expected within 30 days of warranty claim submittal.

We at MFTA regret any inconvenience this situation may cause you. However, your safety and continued satisfaction with our product are most important to us.

If your MFTA Dealer is unable to perform this procedure without charge, or within a reasonable amount of time, please contact MFTA Customer Service toll-free at 877-711-0707 for assistance. You may also contact the Administrator, National Highway Traffic Safety Administration, 400 Seventh St. SW, Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 888-327-4236; (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Sincerely,



William P. Mohr
Director, Service Operations



NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES

BUSINESS REPLY MAIL

FIRST CLASS MAIL PERMIT NO. 26 SOUTHEASTERN, PA

POSTAGE WILL BE PAID BY ADDRESSEE

MITSUBISHI FUSO
TRUCK OF AMERICA, INC.
P.O. BOX 458
SOUTHEASTERN, PA 19399-0458

