



AUGUST 24, 2007

**SAFETY RECALL NOTICE**

**VOLUNTARY SAFETY RECALL CAMPAIGN # 07V-207**

Dear UD Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Nissan Diesel America, Inc. has decided that a defect, which relates to motor vehicle safety, exists in 2005 thru 2007 Model Year UD1800HD, UD2000, UD2300, UD2600 and UD3300 model vehicles produced between January 1, 2004 and December 26, 2006. The vehicle identified on the enclosed "AUTHORIZATION FOR RECALL SERVICE" card fits this description and our records list you as the owner of this vehicle.

Belt tensioner pulley bushing material used on the original belt tensioner or a belt tensioner that was replaced under Safety Recall 06V-159 have insufficient bushing material strength causing abnormal wear that resulted in the binding of the belt tensioner spindle against the spindle bushing. Operating a vehicle with a binding or seized drive belt tensioner may result in the unexpected loss of the engine drive belt and/or cause the drive belt tensioner or mounting bolts to break. If the engine drive belt comes off, the Alternator warning light will illuminate. If the warning light is ignored by the vehicle operator the engine may lose power and eventually stall rendering the vehicle inoperative and increase the risk of a vehicle crash.

Please contact an authorized UD Truck Dealer as soon as possible to schedule an appointment to have the drive belt tensioner replaced at no charge to you. It is estimated that approximately 1.0 hours will be required to complete the repairs.

Federal regulations require that all vehicle lessors must notify all lessees within ten (10) days of receiving this notice.

**IMPORTANT:** We would appreciate your bringing the "AUTHORIZATION FOR RECALL SERVICE" card with you to the UD Truck Dealer at the time of your repair appointment. If you do not have the "AUTHORIZATION FOR RECALL SERVICE" card, please provide the Vehicle Identification Number (VIN) to the UD Truck Dealer when scheduling your appointment to verify that your vehicle requires this recall service.

You may be entitled to reimbursement of costs to repair a previous failure related to this recall. If you believe that you have paid for previous repairs related to this recall, please contact Nissan Diesel America, Inc. at (972) 756 - 5531.

If you no longer own or possess this vehicle, please fill in the requested information on the enclosed postage prepaid "AUTHORIZATION FOR RECALL SERVICE" card and return it to the Nissan Diesel America, Inc. Service Operations Department. This will allow proper identification and notification to the current owner of this vehicle.

You may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, DC 20590 or call the toll free Vehicle Safety Hotline at 1-888 -327- 4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>, if you believe that either Nissan Diesel America, Inc. or the UD Truck Dealer has failed or is unable to repair your vehicle without charge.

We regret any inconvenience this recall may have caused. If you have any questions regarding this recall, you may call the Nissan Diesel America, Inc. Service Operations Department at (972) 756 - 5531.

Sincerely,  
**NISSAN DIESEL AMERICA, INC.**