



NEWMAR

WHEN YOU KNOW THE DIFFERENCE™

December 4, 2007

VEHICLE SAFETY DEFECT SERVICE BULLETIN
Recall Campaign No. 07V-490

Re: Safety Recall -- Villa Isri Air Base Seat

Dear Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Newmar Corp. has decided that certain Newmar Class A Motorhomes manufactured from December 14, 2005 through September 7, 2007, fail to conform to the requirements of Federal Motor Vehicle Safety Standard No. 207, "Seating Systems" and has initiated a voluntary safety recall campaign. This recall campaign has been initiated as the result of a recall notice furnished to the National Highway Traffic Safety Administration ("NHTSA") by seating manufacturer Villa International, as described below.

According to our information, your unit identified on the enclosed form is affected. Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

Newmar Corp. was notified by Villa International that certain air ride driver seats with Isri air suspension and V2500/V2000 ISS ADNIK/VILLA frame manufactured by Villa International between July 2005 and September 17, 2007 fail to conform to Federal Motor Vehicle Safety Standard No. 207, "Seating Systems". The lower slide rails of the air suspension can fail in the event of a vehicle crash, potentially leading to separation of the seat from the seat pedestal which may lead to personal injury of the vehicle occupant(s).

The remedy will involve the installation of two additional front tethers between the air ride adapter plate and the pedestal mount. The recall will be performed at no cost to you. If you had the noncompliance, which is the subject of this letter, remedied prior to receiving this letter, you may be eligible for reimbursement by Newmar Corp. for your remedy costs.

You may contact your Newmar Coach dealer to arrange a service appointment. Instructions for making this correction have been sent to your dealer and the parts are readily available.

The labor time necessary to perform this recall campaign is approximately 0.5 hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your motorhome.

Production numbers of the affected units:

1. 500003
2. 500004
3. 500006
4. 500007
5. 500008
6. 500009
7. 500010
8. 500011
9. 500012
10. 500014
11. 500015
12. 500016
13. 530014 (King Air DB)