



INTERNATIONAL TRUCK AND ENGINE CORPORATION

4201 WINFIELD ROAD, WARRENVILLE, IL 60555

TRUCK GROUP

SAFETY RECALL 07514

FEBRUARY 2008

Dear International Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

International® has decided that a defect which relates to motor vehicle safety exists in certain MXT models built 5/20/2006 thru 7/11/2007.

REASON FOR THIS RECALL

The positive battery cables, that supply power from the batteries to the starter, may be routed near the engine's exhaust manifold. The heat generated by the manifold can cause the cable's insulation to melt, exposing bare wire.

RISK TO MOTOR VEHICLE SAFETY

Exposed bare wire on the battery cable may cause an electrical short and/or fire, which can result in property damage, personal injury, or death.

IF YOU DO NOT OWN THIS VEHICLE

Our records indicate you are the owner of the vehicle identified on the enclosed card. If you do not own this vehicle, please fill out the **Authorization for Recall Service** card so you will not be contacted again regarding this recall.

IF YOU NEED ASSISTANCE

If you believe that International has failed to perform this repair within a reasonable amount of time, or the existing condition was not remedied without charge, please follow the procedure described in the *Owner Assistance Guide* section in your Owner's Manual or call toll free 1-800-448-7825.

You may also wish to submit a complaint to:

Administrator
National Highway Traffic Safety Administration,
1200 New Jersey Avenue, SE
Washington, D.C., 20590

or call the toll-free Vehicle Safety Hot-Line at 1-888-327-4236 (TTY:1-800-424-9152) or go to <http://www.safercar.gov>.

ACTIONS YOU SHOULD TAKE

PLEASE contact your local International dealer to schedule an appointment to have your vehicle repaired. You may locate your nearest International dealer by calling 1-800-44-TRUCK or by visiting:

<http://www.nav-international.com>

The repair will involve a battery cable inspection, replacement if necessary, and rerouting away from the engine exhaust manifold.

Dealers will have parts and instructions to repair your vehicle by 2/8/2008.

This will be performed **free of charge** and may take approximately **90 minutes** to complete.

LESSOR REQUIREMENTS

Federal regulations require that any vehicle lessor receiving this Recall notice must forward a copy of this notice to the lessee within ten days.

We request your prompt attention and patience regarding the correction of this defect and apologize for any inconvenience this may cause you.

Sincerely,

INTERNATIONAL TRUCK AND ENGINE CORPORATION