

SERVICE PROCEDURE

**G-07508
JUNE 2007**

**SUBJECT: SAFETY RECALL (U.S., EXPORT)
RICON® WHEELCHAIR LIFTS on certain BE, CE, FE and
RE School and Commercial Buses built 1/20/2006 thru
9/28/2006**

DEFECT DESCRIPTION

The inboard roll stop interlock may not detect the presence of a “wheelchair test device” when tested in accordance with S7.6 of FMVSS 403.

A shim, installed beneath the interlock switch and/or an improperly routed wire may interfere with the operation of the inboard rollstop switch.

An improperly operating rollstop switch can allow the lift to deploy while not detecting the presence of an occupant. This may cause a wheelchair occupant to tilt backward possibly causing property damage or personal injury.

MODELS INVOLVED

This Safety Recall involves certain BE, CE, FE, and RE school and commercial buses built 1/20/2006 thru 6/28/2006 with RICON® Wheelchair Lift, feature codes:

0049DEK	0049DEP	0049DET	0049DEU
---------	---------	---------	---------

SERVICE PROCEDURE

This Safety Recall is being administered by RICON CORPORATION. Please contact RICON CUSTOMER SUPPORT at 1-800-322-2884 for instructions.

END OF SERVICE PROCEDURE

INTERNATIONAL TRUCK AND ENGINE CORPORATION