


Problem statement...

On certain Starcraft 2007 11RT, 13RT and 14RT frames there is the potential for a coupler/A-frame problem. The best way to identify these units is to measure the width of the top of the coupler (width is 3") and to determine if there is a notch in the side of the tongue. Please refer to the attached pictures.





The repair will require the addition of a steel bracket to help reinforce the coupler/A-frame interface.

