



October 15, 2008

MR. ROBERT BABCOCK
SENIOR MANAGER, REGULATION
AND CERTIFICATION DEPARTMENT
HYUNDAI-KIA AMERICA TECHNICAL CENTER, INC.
6800 GEDDES ROAD
SUPERIOR TOWNSHIP, MI 48198

NVS-215paw 08V-533

SUBJECT: AIR BAG LIGHT ILLUMINATION- WIRING HARNESS MOVEMENT

DEAR MR. BABCOCK:

This letter serves to acknowledge Hyundai Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the products described below for which a safety recall campaign shall be conducted pursuant to 49 U.S.C. § 30119.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HYUNDAI/ELANTRA/2001-2002

NHTSA Campaign Number: 08V-533

Mfg's Report Date: October 10, 2008

Components: AIR BAGS: FRONTAL: SENSOR/CONTROL MODULE

Potential Number of Units Affected: To be provided

Summary:

HYUNDAI IS RECALLING CERTAIN MY 2001-2002 ELANTRA VEHICLES. MOVEMENT OF THE SIDE IMPACT AIR BAG WIRING HARNESS MOUNTED UNDER EACH FRONT SEAT, POSSIBLY CAUSED BY CONTACT FROM MATERIALS PLACED UNDER THE SEAT, MAY RESULT IN AN ELECTRICAL RESISTANCE THAT WOULD CAUSE SUPPLEMENTAL RESTRAINT SYSTEM (SRS) WARNING LIGHT ILLUMINATION.

Consequence:

THIS CONDITION ONLY RELATES TO THE DRIVER AND PASSENGER SEAT MOUNTED SIDE IMPACT AIR BAGS AND MAY PREVENT SEAT MOUNTED SIDE IMPACT AIR BAG DEPLOYMENT DURING A CRASH WHERE SUCH DEPLOYMENT SHOULD OCCUR. NON-DEPLOYMENT OF THE SRS AIR BAGS MAY INCREASE THE RISK OF INJURY TO THE DRIVER AND FRONT PASSENGER UNDER CERTAIN CRASH CONDITIONS.

Remedy:

DEALERS WILL INSTALL NEW SIDE IMPACT AIR BAG WIRING HARNESS CONNECTOR CLIPS AND REVISED SIDE IMPACT AIR BAG WIRING HARNESS ATTACHMENTS UNDER THE DRIVER'S AND FRONT PASSENGER'S SEATS. THE RECALL IS EXPECTED TO BEGIN DURING THE FOURTH QUARTER OF 2008, AND WILL BE SENT OUT IN SIX MAILINGS. OWNERS MAY CONTACT HYUNDAI AT 1-800-633-5151.

Notes:

HYUNDAI RECALL NO. 088. CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO HTTP://WWW.SAFERCAR.GOV.

This recall was the subject of an Engineering Analysis, EA08-012, conducted by the Office of Defects Investigation.

We have reviewed your proposed owner notification letter and it meets the requirements of Part 577.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6 except for the following items:

Please provide us with the number of 2001-2002 Elantra vehicles involved in this campaign which were built from April 27, 2001 through December 18, 2001.

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at Patricia.wallace@dot.gov, Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

George H. Person

Chief, Recall Management Division

Office of Defects Investigation

Enforcement