



*Driven to Explore*

July 20, 2009

Fleetwood Enterprises, Inc.  
3125 Myers Street / Riverside, CA 92503-5527  
P.O. Box 7638 / Riverside, CA 92513-7638  
p: 909.351.3500 / www.fleetwoodrv.com

Mr. Daniel C. Smith  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
1200 New Jersey Ave, SE  
Washington, DC 20590

Re: Amended Safety Defect Report - Campaign 08V-503

Dear Mr. Smith:

On September 10, 2008, Fleetwood Enterprises, Inc., decided that a safety defect which relates to motor vehicle safety exists in certain motor homes as listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Non-compliance reports.

The following is the information required by 49 CFR Part 573:

- This report was prepared on September 15, 2008.
- Fleetwood has assigned 80912 as an identification code to this recall.

(1) The affected motor homes were manufactured by the following wholly owned subsidiaries of Fleetwood Enterprises, Inc.

Fleetwood Motor Homes of California, Inc. #47  
5300 Via Ricardo, P.O. Box 5726  
Riverside, California 92517

The agency should contact the following individual with respect to this recall:

Chuck James  
Director – Parts & Service  
Motor Home Division  
1010 Commerce Dr., P.O. Box 1007  
Decatur, Indiana 46733  
Telephone: 260-728-9564  
Fax: 260-724-5988

(2) The vehicles involved in the recall are certain 2008 and 2009 model year Tioga, Tioga SL Jamboree, Jamboree GT, Pulse and Icon class C model motor homes manufactured from:  
Tioga - April 27, 2007 through September 5, 2008  
Tioga SL - June 8, 2007 through July 12, 2008  
Jamboree - April 10, 2007 through September 26, 2008

Jamboree GT - June 22, 2007 through July 15, 2008

Pulse - September 28, 2007 through March 21, 2008

Icon - September 28, 2007 through March 21, 2008

These motor homes were built with a Fleetwood identification number range of:

Tioga 30H	741H84797046 through 741H94799836
Tioga 26J	741J84797043 through 741H94700428
Tioga 31K	741K84798956 through 741K84799506
Tioga 31M	741M84700017 through 741M94799832
Tioga 28T	741T84797600 through 741T84799516
Tioga 31W	741W84797835
Tioga	877W84796901 through 877M84796905

Tioga SL 30H	763H84797842 through 763HY84798932
Tioga SL 30L	763L84797750 through 763L84798012
Tioga SL 30U	763U84797543 through 763U94799834
Tioga SL 31W	763W84700003 through 763W94700790

Jamboree 30H	751H84797524 through 751H84798939
Jamboree 26J	751J84797173 through 751J94799833
Jamboree 31K	751K84797868 through 751K84798959
Jamboree 31M	751M84700006 through 751M94701048
Jamboree 28T	751T84797853 through 751T84798962

Jamboree GT 30H	773H84797478 through 773H84799207
Jamboree GT 31L	773L84797739 through 773L84799327
Jamboree GT 30U	773U84700014 through 773U94700793
Jamboree GT 31W	773W84797045 through 773W94799835

Pulse 24A	765A84799285 through 765A94799970
Pulse 24D	765D84798976 through 765D94799974

Icon 24A	766A84799286 through 766A94799969
Icon 24D	766D84798977 through 766D94799978

- (3) Fleetwood reports approximately 979 as the number of motor homes that contain the safety defect.
- (4) Fleetwood estimates that 100% of the affected motor homes contain the safety defect.
- (5) On certain 2008 and 2009 Tioga, Tioga SL, Jamboree, Jamboree GT, Pulse and Icon class C motor homes affected by this recall, the front clearance lights wiring may come in contact with a portion of the metal mounting plate and may become abraded which may result in a fire.

- (6) Not applicable.
- (7) Fleetwood began an investigation in September 2008 after a Fleetwood dealer reported the problem.

Fleetwood is not aware of any accidents or injuries that have resulted from this safety defect.

- (8) Fleetwood will inspect and if necessary install a plastic snap bushing to prevent the wiring from becoming abraded.
- (9) Fleetwood intends to conduct a dealer notification by e-mail in February, 2009.


Fleetwood intends to conduct a customer notification by UPS traceable in February, 2009.

Fleetwood does not foresee any problems with implementing this voluntary recall campaign.

- (10) Copies of subsequent correspondence will be submitted to the NHTSA within five (5) working days of distribution. This correspondence will include:
- I) Letter of dealer notification
  - II) Letter of customer notification
  - III) Service Bulletin

A draft of these documents will be forthcoming for your review. If additional information is required, please contact Dave Fortney who can be reached by phone at (260) 724-5957 or by e-mail at [dave.fortney@fleetwood.com](mailto:dave.fortney@fleetwood.com).

Sincerely,



Chuck James  
Director of Parts & Service  
Motor Home Division