



January 22, 2009

Fleetwood Enterprises, Inc.  
3125 Myers Street / Riverside, CA 92503-5527  
P.O. Box 7638 / Riverside, CA 92513-7638  
p: 909.351.3500 / www.fleetwoodrv.com

Mr. Daniel C. Smith  
Associate Administrator for Enforcement  
National Highway Traffic Safety Administration  
1200 New Jersey Ave, SE  
Washington, DC 20590

Re: **Amended Safety Defect Report - Campaign 08V-503**

Dear Mr. Smith:

On September 10, 2008, Fleetwood Enterprises, Inc., decided that a safety defect which relates to motor vehicle safety exists in certain motor homes as listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Non-compliance reports.

The following is the information required by 49 CFR Part 573:

- This report was prepared on September 15, 2008.
  - Fleetwood has assigned 80912 as an identification code to this recall.
- (1) The affected motor homes were manufactured by the following wholly owned subsidiaries of Fleetwood Enterprises, Inc.

Fleetwood Motor Homes of California, Inc. #47  
5300 Via Ricardo, P.O. Box 5726  
Riverside, California 92517

The agency should contact the following individual with respect to this recall:

Chuck James  
Director – Parts & Service  
Motor Home Division  
1010 Commerce Dr., P.O. Box 1007  
Decatur, Indiana 46733  
Telephone: 260-728-9564  
Fax: 260-724-5988

- (2) The vehicles involved in the recall are certain 2008 and 2009 model year **Tioga**, Tioga SL **Jamboree**, Jamboree GT, **Pulse and Icon** class C model motor homes manufactured from:
- Tioga - April 27, 2007 through September 5, 2008**  
**Tioga SL - June 8, 2007 through July 12, 2008**  
**Jamboree - April 10, 2007 through September 26, 2008**

Jamboree GT - June 22, 2007 through July 15, 2008  
Pulse - September 28, 2007 through March 21, 2008  
Icon - September 28, 2007 through March 21, 2008

These motor homes were built with a Fleetwood identification number range of:

Tioga 30H 741H84797046 through 741H94799836  
Tioga 26J 741J84797043 through 741H94700428  
Tioga 31K 741K84798956 through 741K84799506  
Tioga 31M 741M84700017 through 741M94799832  
Tioga 28T 741T84797600 through 741T84799516  
Tioga 31W 741W84797835  
Tioga 877W84796901 through 877M84796905

Tioga SL 30H 763H84797842 through 763HY84798932  
Tioga SL 30L 763L84797750 through 763L84798012  
Tioga SL 30U 763U84797543 through 763U94799834  
Tioga SL 31W 763W84700003 through 763W94700790

Jamboree 30H 751H84797524 through 751H84798939  
Jamboree 26J 751J84797173 through 751J94799833  
Jamboree 31K 751K84797868 through 751K84798959  
Jamboree 31M 751M84700006 through 751M94701048  
Jamboree 28T 751T84797853 through 751T84798962

Jamboree GT 30H 773H84797478 through 773H84799207  
Jamboree GT 31L 773L84797739 through 773L84799327  
Jamboree GT 30U 773U84700014 through 773U94700793  
Jamboree GT 31W 773W84797045 through 773W94799835

Pulse 24A 765A84799285 through 765A94799970  
Pulse 24D 765D84798976 through 765D94799974

Icon 24A 766A84799286 through 766A94799969  
Icon 24D 766D84798977 through 766D94799978

- (3) Fleetwood reports approximately 893 as the number of motor homes that contain the safety defect.
- (4) Fleetwood estimates that 100% of the affected motor homes contain the safety defect.
- (5) On certain 2008 and 2009 Tioga, Tioga SL, Jamboree, Jamboree GT, Pulse and Icon class C motor homes affected by this recall, the front clearance lights wiring may come in contact with a portion of the metal mounting plate and may become abraded which may result in a fire.

- (6) Not applicable.
- (7) Fleetwood began an investigation in September 2008 after a Fleetwood dealer reported the problem.

Fleetwood is not aware of any accidents or injuries that have resulted from this safety defect.

- (8) Fleetwood will inspect and if necessary install a plastic snap bushing to prevent the wiring from becoming abraded.

- (9) Fleetwood intends to conduct a dealer notification by e-mail in **February, 2009**.

Fleetwood intends to conduct a customer notification by UPS traceable in **February, 2009**.


Fleetwood does not foresee any problems with implementing this voluntary recall campaign.

- (10) Copies of subsequent correspondence will be submitted to the NHTSA within five (5) working days of distribution. This correspondence will include:

- I) Letter of dealer notification
- II) Letter of customer notification
- III) Service Bulletin

A draft of these documents will be forthcoming for your review. If additional information is required, please contact Shelley Krueger who can be reached by phone at (951) 351-3646 or by e-mail at [skrueger@fleetwood.com](mailto:skrueger@fleetwood.com).

Sincerely,



Chuck James  
Director of Parts & Service  
Motor Home Division