

**** ADVANCE TECHNICAL INFORMATION NOTICE ****

DATE: March 10, 2008
TO: U.S. Mitsubishi Motors Service Managers
RE: Safety Recall SR-08-001
ATIN NO. ATIN-08-SR-001

AFFECTED VEHICLES: 2006-07 Endeavor built between July 10, 2006 and February 16, 2007.

Safety Recall Bulletin **SR-08-001** is being mailed to all dealers today for two-day air delivery. It will also be available on MEDIC and the Mitsubishi Dealer Link for download today.

The passenger's side (right hand) seat belt assembly must be replaced on affected vehicles with a modified part. The dealer bulletin mailing will include a list of affected VINs shown as being in their new vehicle inventory on February 20, 2008.

Owners of the affected vehicles will be notified by mail, asking them to bring their vehicle to a Mitsubishi dealer for this repair.

IMPORTANT

Affected new or used inventory vehicles must be repaired BEFORE THE VEHICLE IS SOLD. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is an affected VIN for this safety recall.