



Safety Recall ALERT

Date: January 31, 2008 **Number:** SRA-07-08
To: All U.S. & Canadian Distributors
Attention: Service Manager, Warranty Manager, Parts Manager, Dealer Principal
From: Regulatory Affairs Department
Subject: Safety Recall, RVXX0708, Diesel Particulate Filter Inhibit Switch

Safety Recall Summary:

On certain Volvo VNL and VT model vehicles manufactured from March 2007 through July 2007, an incorrect software parameter was loaded which resulted in the Diesel Particulate Filter (“DPF”) “inhibit” function being disabled. The “inhibit” function is a means for the driver to stop a DPF regeneration from occurring if a vehicle is in a location that may present a hazardous situation.

The number of vehicles affected is approximately 902 (798 US; 101 Canada; 3 Export).

Dealer’s Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Repair Instructions are tentatively scheduled for release no later than February 8, 2008.
- Vehicle list is tentatively scheduled to be posted on the Trucks Dealer Portal January 31, 2008.
- Owner Notices are scheduled to be mailed on or before February 15, 2008.

Questions:

Contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com if you have questions.