




## SIMPLEX FIFTH WHEEL FIELD CAMPAIGN NOTIFICATION

This notification is to make you aware of a field campaign that SAF-HOLLAND is undertaking to replace a spacer in the lever bar connection that could affect the timing of the fifth wheel's lock mechanism. This is **NOT** a safety related issue as this condition is evident to the driver when visually inspecting the release handle and position of the red indicator in accordance with the proper coupling procedure.

The Simplex fifth wheels that should be inspected were manufactured between January 3, 2006 and July 2, 2007. Visually inspect the cover plate/lever bar connection on the underside of the fifth wheel. The fifth wheel is **affected** if a hex-head fastener is used to secure the connection as shown in Figure 1. The fifth wheel is **unaffected** if a pin is used to secure the connection as shown in Figure 2.


**FIGURE 1 – AFFECTED UNIT**

**HEX-HEAD BOLT CONNECTION**



**FIGURE 2 – UNAFFECTED UNIT**

**PIN CONNECTION**



If you have a fifth wheel that matches the image in Figure 1, we strongly encourage you to contact us for a repair kit(s), free of charge, at (888) 396-6501 ext 4343. Be prepared to provide: serial number of the wheel, VIN # of the vehicle, date and service. If you have any questions concerning this notification, please ask for technical assistance when you contact us.