

Audi of America, Inc.

UPCOMING SAFETY RECALL INFORMATION

Audi of America, Inc.
3800 Hamlin Road
Auburn Hills, MI 48326
United States of America
www.audiusa.com

June 2, 2008

Subject: Information Update – Safety Recall JY

Dear Audi Dealer Principal, Service Manager, and Parts Manager:

We are writing to supplement our letter announcing this recall that we sent you in April regarding the upcoming safety recall on potential fuel leaks in some 2001-2004 model year Audi A6 quattro and some model year 2001-2005 allroad quattro vehicles.

What is the problem?

The aging of the plastic material in the fuel tank rollover valve – combined with bending stress from the aluminium ventilation line to the rollover valve nipple – may lead to cracking of the nipple. If this happens, a fuel leak may result. A fuel leak in the presence of an ignition source could lead to a vehicle fire.

What does the repair involve and when will the repair be available?

To prevent or repair cracking at the nipple, dealers will reinforce the nipple on the rollover valve on the affected vehicles at no cost to customers.

Due to some parts constraints, Audi now expects that dealer notification will take place on or about June 23, 2008. Customer notification will take place on or about June 27, 2008.

In the interim, affected vehicles presented for service at an authorized Audi dealer with a fuel leak at the rollover valve nipple will be repaired at no cost to customers. Please contact the Campaign Helpline at 1-800-741-2919 for approval and claiming instructions.

Parts Allocation Information

You will receive an initial allocation of parts for this campaign prior to the initiation of this safety recall.

As always, any press/media related questions should be directed to Christian Bokich at the Audi public relations team. Christian can be reached at (248) 754-4729.

Any customers with questions unable to be answered by this announcement should be directed to Audi Customer CARE at 1-800-253-2834.

Thank you for your help in this matter.

Audi Product Compliance