

September 8, 2008

**TO: ALL HYUNDAI DEALER PRINCIPALS/GENERAL MANAGERS:  
ALL HYUNDAI DEALERSHIP SERVICE MANAGERS:  
ALL HYUNDAI DEALERSHIP PARTS MANAGERS:  
ALL HYUNDAI DEALERSHIP SALES MANAGERS:**

**SUBJECT: Campaign 086 - 2008 Elantra (HD) - Fuel Pump Sub-Assembly  
Replacement - TSB #08-01-011-1**

Hyundai Motor America is conducting a Customer Notification for replacement of the Fuel Pump Sub-Assembly campaign on selected 2008 Model Year Elantras. This Customer Notification replaces previously announced Service Campaign T57 (TSB# 08-01-011).

This campaign provides a procedure for replacement of the fuel pump assembly.

In order to identify only those vehicles affected by Campaign 086, it will be necessary to access Hyundai Motor America's "Warranty Vehicle Information" screen via DCS On-line or WEBDCS before starting the repair. The "Warranty Vehicle Information" screen will identify affected vehicles with an open Campaign 086. All in-stock vehicles, if any, must have Campaign 086 completed prior to retailing.

Enclosed with the Service Manager's letter are materials, which were developed for your use: Dealer Letter, five (5) copies of the Technical Service Bulletin (TSB#08-01-011-1) containing instructions on performing the service and submitting the campaign claim, and a VIN listing of your dealer stock vehicles only. TSB #08-01-011-1 will be available on Hyundai's Website on September 8, 2008.

**All Hyundai dealers were previously shipped updated parts (Fuel Pump Assemblies) for 100% of their in-stock vehicles starting the week of August 18, 2008 as part of Service Campaign T57. Additional fuel pump assemblies can be ordered from your facing PDC.**

Customer notification letters will be mailed in three weekly flights starting September 15, 2008.

It is IMPORTANT TO SUBMIT A CAMPAIGN CLAIM FOR EACH VEHICLE SERVICED so your dealership can be compensated for your work and Hyundai can maintain accurate records of campaign completions. **Repair Orders dated August 18, 2008 through September 7, 2008 should follow procedures as outlined in TSB# 08-01-011. Repair Orders dated September 8, 2008 and later should follow procedures outlined in TSB# 08-01-011-1.**

**LEGAL LIABILITY NOTICE:** You are required to keep confidential any and all information and documents provided to you by Hyundai Motor America in the conduct of carrying out work for this service campaign. Hyundai Motor America dealers may use owner information provided for the campaign only for the purpose of conducting and performing this service campaign, and for no other purpose.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA