



December 18, 2008

Ms. Patricia Wallace

National Highway Traffic Safety Administration  
ODI/Recall Management Division - NVS-215  
1200 New Jersey Avenue S.E.  
Washington, DC 20590

Via FedEx

Re: Nissan Diesel America, Inc.

Dear Ms. Wallace:

I am forwarding the following information for the Safety Recall 08V-617 for your review and approval:

1. Customer Notification Letter
2. UD Truck Dealer Notification Letter
3. Dealer Safety Recall Bulletin 08V-617

We anticipate the UD Truck Dealer to be mailed on January 5, 2009 and the Owner Notification to be mailed on January 19, 2009.


Please contact me if you have any questions at 972-756-5523.

Sincerely,

Les Wells  
Senior Manager  
Warranty-Service Operations  
[lwells@nissandiesel.com](mailto:lwells@nissandiesel.com)

C O R P O R A T E O F F I C E

P.O. Box 152034, Irving, Texas 75015-2034 • 5930 West Campus Circle Drive, Irving, Texas 75063  
Telephone 972-756-5500 • Fax 972-550-1255  
<http://www.udtrucks.com>



**TRUCKS**  
Nissan Diesel America, Inc.

**Date:** January 5, 2009  
**To:** Dealer Principal  
Dealer Service Manager  
**From:** Service Operations Department  
**Re:** Notification Letter for Voluntary Safety Recall Campaign # 08V-617

Nissan Diesel America, Inc. has decided that a defect, which relates to motor vehicle safety, exists in the 2008 Model Year UD1800HD, UD2000, UD2300, UD2600 and UD3300 model vehicles produced between August 7, 2006 and October 1, 2007.

The fuel injection pump drive coupler installed between the fuel injection pump and the engine air compressor on the above subject vehicles may experience a failure as a result of improper machining. The improperly machined fuel injection pump drive coupler could crack without warning under normal vehicle operation. Continued operation with a cracked drive coupler could result in the coupler becoming broken and causing the engine to stall and not restart.

Dealers are requested to proceed immediately to make the necessary repair to the affected vehicles in inventory. **It is a violation of federal law for a dealer to deliver a new motor vehicle covered by a recall notice until the recall remedy has been performed.** Each dealer will receive a computer listing of all affected vehicles in either unsold/undelivered inventory or retail delivered to customers. With this updated computer listing, the dealer will receive a postage prepaid "AUTHORIZATION FOR RECALL SERVICE" card for all unsold or undelivered inventory. This postage pre-paid card must be filled out correctly and returned to the address on the card indicating whether the vehicle was repaired, transferred, sold, etc. (refer to the UD Warranty Policies & Procedures Manual, Part III, Section 1). For vehicles without an "Authorization for Recall Service" card, check the vehicle identification number with the Vehicle Service Notification screen of the NDAINET Warranty Claim System menu to verify that it requires the safety recall.

Safety Recall Parts are available immediately through the NDA Parts Operations Department. Dealers should base their parts order on the number of unsold/undelivered vehicles and of retail delivered vehicles that appear on the computer listing.

Federal regulations require that all vehicle lessors must notify all lessees within ten (10) days of receiving this notice.

Repairs to correct this condition consist of replacing the fuel injection pump drive coupler. We estimate that approximately 4.0 hours will be required to complete the repairs. After the repairs have been performed, please return the postage prepaid "AUTHORIZATION FOR RECALL SERVICE" card to Nissan Diesel America, Inc. Service Operations Department.

All owners of affected vehicles will be notified by mail to schedule an appointment with an authorized UD Truck Dealer to have this safety recall performed free of charge.

Please find the following information enclosed with this letter:

- Recall Bulletin # 08V-617 dated January 5, 2009.
- Computer list of unsold/undelivered dealer inventory and retail delivered vehicles sold by or assigned to your dealership.
- Unmatched "AUTHORIZATION FOR RECALL SERVICE" cards for unsold inventory vehicles.
- Customer Notification Letter dated January 19, 2009.

Complete details and procedures for this safety recall may be found in Recall Bulletin # 08V-617 issued with this letter. Recall Bulletin # 08V-617 is also posted on the Service website of the NDAINET and additional copies of the bulletin are available upon request. Any questions concerning this safety recall may be directed to the Technical Support Manager or any of the Service Operations staff at Nissan Diesel America, Inc.