

February 20, 2008

VIN: _____

SUBJECT: SAFETY RECALL # 1207L
Eaton Synflex Eclipse Tubing
EXPIRATION DATE: NONE

Dear Peterbilt Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Peterbilt Motors has decided that certain model year 2008 vehicles manufactured between October 7, 2007 and November 9, 2007 fail to conform to Federal Motor Vehicle Safety Standard No. 106, "*Brake Hoses*". Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

Eaton notified Peterbilt Motors that 5 lots of extruded nylon tubing do not have the proper wall thickness. These suspect nylon tubes connect various components of the vehicles' air system to each other, including the air brake system. A defective tube may leak air at the air tube fitting. In the event of an excessive air leak, the system will provide an audible alarm that the spring brakes will activate and the vehicle will come to a stop. Operating the vehicle with the spring brakes activated can incur excessive wear or damage to your equipment.

<i>The problem is...</i>	Defective air system tubing
<i>What your dealer will do...</i>	Replace suspect nylon tubing
<i>What you must do ...</i>	Contact your dealer immediately to schedule an appointment

Peterbilt Motors Company has initiated a recall to replace suspect nylon tubing. Please contact your Peterbilt dealer immediately to schedule an appointment. This should take no more than a few 4.5 hours to replace. These services will be provided at no charge to you.

If you require further information, have already experienced this condition and have paid to have it repaired, or experience any difficulty in making arrangements for the repair, please contact: Peterbilt Motors Company, 1700 Woodbrook Street, Denton, Texas 76205; Customer Service Department, phone 940-591-4196.


If you conclude that Peterbilt Motors Company has not enabled you to remedy this defect within a reasonable time and without charge, you may submit a complaint to: Administration for Safety Assurance, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC 20590, or call the toll free safety hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Rick Wood
Quality Services Manager

February 22, 2008

Subject: 07KWF – Eaton Synflex Air Tubing
Vin No.

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Kenworth Truck Company in conjunction with Eaton has decided that certain model year 2008 Kenworth vehicles manufactured between October 2, 2007 and November 9, 2007, fail to conform to Federal Motor Vehicle Safety Standard No. 106, "Brake Hoses". Your vehicle has been identified as having been manufactured within this time period and may contain a defect.

Eaton notified Kenworth Truck Company that 5 lots of extruded nylon tubing do not have the proper wall thickness. These suspect nylon tubes connect various components of the vehicles' air system to each other, including the air brake system. A defective tube may leak air at the air tube fitting. In the event of an excessive air leak, the system will provide an audible alarm that the spring brakes will activate and the vehicle will come to a stop. Operating the vehicle with the spring brakes activated can incur excessive wear or damage to your equipment.

<i>The problem is...</i>	Defective nylon air system tubing.
<i>What your dealer will do...</i>	Replace suspect nylon tubing.
<i>What you must do ...</i>	Contact your dealer immediately to schedule an appointment.

Kenworth has initiated a recall to replace suspect nylon tubing. Please contact your Kenworth dealer immediately to schedule an appointment for this inspection. To find your nearest Kenworth dealer, please visit Dealer Locator at www.Kenworth.com. This procedure should take no more than six hours to replace, and will be performed at no charge to you. If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

If you require further information about this recall, reimbursement of a pre-notification remedy associated with this recall or experience any difficulty in making arrangements for this repair, please contact: Kenworth Truck Company, P.O. Box 1000, Kirkland, WA 98083-1000, Attn: Customer Service Department, phone 425-828-5000.

If you conclude that Kenworth Truck Company has not enabled you to remedy this defect in reasonable time and without charge, you may submit a complaint to: Administrator for Safety Assurance, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, DC 20590, or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience that this work may cause you and appreciate your cooperation in this matter.

Sincerely,

Mike Kalkoske
Quality Services Manager