



JANUARY 19, 2009

SAFETY RECALL NOTICE

VOLUNTARY SAFETY RECALL CAMPAIGN # 08V-617

Dear UD Truck Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Nissan Diesel America, Inc. has decided that a defect, which relates to motor vehicle safety, exists in the 2008 Model Year UD1800HD, UD2000, UD2300, UD2600 and UD3300 model vehicles produced between August 7, 2006 and October 1, 2007. The vehicle identified on the enclosed "AUTHORIZATION FOR RECALL SERVICE" card fits this description and our records list you as the owner of this vehicle.

The fuel injection pump drive coupler installed between the fuel injection pump and the engine air compressor on the above subject vehicles may experience a failure as a result of improper machining. The improperly machined fuel injection pump drive coupler could crack without warning under normal vehicle operation. Continued operation with a cracked drive coupler could result in the coupler becoming broken and causing the engine to stall and not restart; which could result in a crash without warning to the vehicle operator.

Please contact an authorized UD Truck Dealer as soon as possible to schedule an appointment to have the fuel injection pump drive coupler replaced at no charge to you. It is estimated that approximately 4.0 hours will be required to complete the repairs.

Federal regulations require that all vehicle lessors must notify all lessees within ten (10) days of receiving this notice.

IMPORTANT: We would appreciate your bringing the "AUTHORIZATION FOR RECALL SERVICE" card with you to the UD Truck Dealer at the time of your repair appointment. If you do not have the "AUTHORIZATION FOR RECALL SERVICE" card, please provide the Vehicle Identification Number (VIN) to the UD Truck Dealer when scheduling your appointment to verify that your vehicle requires this recall service.

You may be entitled to reimbursement of costs to repair a previous failure related to this recall. If you believe that you have paid for previous repairs related to this recall, please contact Nissan Diesel America, Inc. at (972) 756 - 5531.

If you no longer own or possess this vehicle, please fill in the requested information on the enclosed postage prepaid "AUTHORIZATION FOR RECALL SERVICE" card and return it to the Nissan Diesel America, Inc. Service Operations Department. This will allow proper identification and notification to the current owner of this vehicle.

You may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590 or call the toll free Vehicle Safety Hotline at 1-888 -327- 4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>, if you believe that either Nissan Diesel America, Inc. or the UD Truck Dealer has failed or is unable to repair your vehicle without charge.

We regret any inconvenience this recall may have caused. If you have any questions regarding this recall, you may call the Nissan Diesel America, Inc. Service Operations Department at (972) 756 - 5531.

Sincerely,
NISSAN DIESEL AMERICA, INC.

C O R P O R A T E O F F I C E

P.O. Box 152034, Irving, Texas 75015-2034 • 5930 West Campus Circle Drive, Irving, Texas 75063

Telephone 972-756-5500 • Fax 972-550-1255

<http://www.udtrucks.com>