



October 16, 2008

Mr. Daniel C. Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Ave, SE
Washington, DC 20590

Fleetwood Enterprises, Inc.
3125 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92513-7638
p: 909.351.3500 / www.fleetwoodrv.com

Dear Mr. Smith:

This letter is written to notify the NHTSA that Fleetwood Enterprises, Inc., is aware of the voluntary initiation of a recall notification campaign affecting Fleetwood produced recreational vehicles as listed below:

Class C Motor Homes - Model Year 2009

Pulse manufactured 4/11/08 through 6/26/08
Icon manufactured 4/4/08 through 4/7/08

This voluntary recall campaign is being conducted by:

**Sprinter Engineering
A Division of MBUSA, LLC
8501 Palmetto Commerce Pkwy
Ladson, SC 29456**

Telephone: (843) 695-5000

This voluntary recall campaign involves approximately 8 Fleetwood Class C motor homes manufactured with Sprinter chassis.

Fleetwood estimates that 3% of the above motor homes contain the safety defect. This is based on the Part 573 defect report that Sprinter Engineering submitted to the National Highway Traffic Safety Administration on July 23, 2008.

The reason for the recall is that on some Sprinter 3500 chassis, the left drive shaft of the rear axle labeled with the charge indicator "S" may contain cracks at the radius between the shaft and the flange. These cracks may cause a breakage of the drive shaft. This could cause a loss of power and result in a crash without warning.

Fleetwood has no reason to disagree with this action or the recall remedy. Fleetwood is relying on Sprinter Engineering and the NHTSA to monitor campaign performance.

Fleetwood has notified all Fleetwood owners of record involved in this campaign.

Sincerely,

Chuck James
Director – Parts & Service
Motor Home Division

Cc: Wolf-Dieter Kleimeier - Sprinter Engineering and Compliance Support Team