

Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.7

Report Date October 27th 2009
Calendar Quarter 4

Date in (yyyy-mm-dd) format

Manufacturer Prevost
Report Author Dominique Gagnon
Phone 418-831-5432 x 235
E-mail dominique.gagnon@volvo.com

	NHTSA Recall Number	Canada DOT recall Number	Prevost Recall #	Description	Date notification to purchasers began	Date notification to purchasers was completed	Safety Recall Quarterly Report ...		Total Number of Vehicles/Pces of Equipment Involved			Total Number Inspected & Remedied			Completion Rate (%), per country			Total Number Inspected & NOT REQUIRING REMEDY	Vehicles determined to be Unreachable	For internal use only: Nb of years reporting the recall...	Comments
							From...	Through...	USA	Canada	Total	USA	Canada	Total	USA	Canada	Total				
1	01V-035	01-086	SR01-03	Front Axle Transversal Radius Rod Attachment Assembly	2001-02-16	2001-02-16	2001-02-16	2009-10-27	241	159	400	130	95	225	54%	60%	56%	0%	0%	8.8	Renotification to customers sent April 2008.
2	05V-107	05-073	SR05-07	Insp. & Repl. Power Steer. Hoses	2005-03-09	2005-03-09	2005-03-09	2009-10-27	473	188	661	303	140	443	64%	74%	67%	0%	0%	4.7	
3	05V-516	05-374	SR05-14A	Windshield Wiper Motor	2005-11-03	2005-11-03	2005-11-03	2009-10-27	122	53	175	96	37	133	79%	70%	76%	0%	0%	4.0	
4	06V-214	06-252	SR06-07A	Bell Crank And Idler Arm Mounting Spindle	2006-06-09	2006-06-09	2006-06-09	2009-10-27	412	35	447	357	28	385	87%	80%	86%	0%	0%	3.4	
5	06V-243	06-251	SR06-10	Bendix SR-7 Spring Brake Valve	2006-11-03	2006-11-03	2006-11-03	2009-10-27	8	1	9	6	0	6	75%	0%	67%	0%	0%	3.0	
6	08V-007	08-006	SR07-10	ZF Trans. Gear Shifter Defect	2008-01-21	2008-01-21	2008-01-09	2009-10-27	383	82	465	185	23	208	48%	28%	45%	0%	0%	1.8	
7	07V-371	07-284	SR07-11	Bendix SR-7 Internal Check Valve Replacement	2007-09-20	2007-09-20	2007-09-20	2009-10-27	673	164	837	516	129	645	77%	79%	77%	0%	0%	2.1	
8	08V-448	08-356	SR08-12	Replacing Weakened Bolts On Roof Escape Hatch	2008-10-20	2008-10-20	2008-10-20	2009-10-27	118	72	190	98	54	152	83%	75%	80%	0%	0%	1.0	
9	08V-597	08-405	SR08-21	Passenger Seats Pedestal, Ass. Fixing Screws	2008-12-15	2008-12-15	2008-12-15	2009-10-27	58	23	81	29	10	39	50%	43%	48%	0%	0%	0.9	
10	08V-610	08-430	SR08-22A	Power Steering Hose	SR0822 sent out 2009-03-09	SR0822revA sent out 2009-05-01	2009-03-09	2009-10-27	455	182	637	328	60	388	72%	33%	61%	0%	0%	0.6	
11	09V-061	n/a, US recall only	SR09-04	REPLAC. LOWER A-ARMS FIX. BOLTS	2009-02-20	2009-02-20	2009-02-20	2009-10-27	22	0	22	17	n/a	17	77%	n/a	77%	0%	0%	0.7	Recall only applicable to USA
12	09V-190	09-152	SR09-09	INSP. & REPL. DRAG LINK TIE ROD END	2009-06-30	2009-06-30	2009-06-30	2009-10-27	49	14	63	26	4	30	53%	29%	48%	0%	0%	0.3	
13	09E-035	09-155	SR09-10	INSP. & REPL. DRAG LINK TIE ROD END	2009-06-30	2009-06-30	2009-06-30	2009-10-27	17	7	24	0	2	2	0%	29%	8%	0%	0%	0.3	Recall applicable to parts sold in After-Market

Comments:

October 27 2009: Thank you.
 July 17th 2009: Thank you.
 April 28th 2009: No comment
 Feb 11th 2009: Please observe that Canada DOT recall number for Prevost Safety recall SR08-22 is 08-430 and not 08-429.