



Hyundai de Puerto Rico c/o Sojitz de Puerto Rico Corp.
P.O. Box 2006 Cataño, PR 00963-2006
Tel: (787) 999-4310 Fax: (787) 251-3232
www.hyundaipr.com

July 22, 2009

Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Att: Recall Management Division (NVS-215)
1200 New Jersey Avenue, SE
Washington, D.C. 20590

**Re: NHTSA Campaign No. 08V-694 – Fuel Pump Sub Assembly
2nd Quarter Report.**

Hyundai of Puerto Rico, c/o Sojitz de Puerto Rico submits this letter for purposes of compliance with the quarterly reporting requirements of 49 C.F.R. Section 573.7. The following information is submitted for the calendar quarter ending June 30, 2009. This recall involves the following vehicles distributed by Hyundai of Puerto Rico: ***2008 Hyundai Elantra vehicles with 2.0 liter Beta engines produced beginning November 5, 2007 through June 28, 2008 and equipped with fuel pumps manufactured with upper body components from a different supplier than those manufactured prior to November 5, 2007.***

The following information is identified by and in the order of the paragraph headings of Section 573.7(b):

1. The notification campaign number assigned by NHTSA: ***No. 08V-694***
2. Date of notification began and the date completed: ***Notification to customers begun and completed on February 9, 2009.***
3. Number of vehicles involved in the campaign: ***347***
4. The number of vehicles and equipment items, which have been inspected and repaired and the number of vehicles and equipment items inspected and determined there is no need to repair:

a. Inspected & Repaired	76
b. Inspected and determined no need to repair	0

08V-694

5. The number of vehicles determined to be unreachable for inspection due to export, theft, scrapping, failure to receive notification or other reasons. As of June 30, 2009, the number of vehicles determined to be unreachable for inspection due to:

a. Export	0
b. Theft	0
c. Scrapping	0
d. Failure to receive notice (Undeliverable mail) *	112
e. Others	0

*Returned notification letters are been sent to Sales Dealer to contact owners of affected units through the sales registration address information, home/work telephone and/or cellular number.

If you require any additional information, please do not hesitate to contact the undersigned at (787) 999-4310 ext. 2440

Sincerely,

Jose Carreras
Service Engineer
Service Department, HdPR

C: R. García, EVP. & COO. - HdPR
R. Arzuaga, Service Manager - HdPR

08V-694