



Fleetwood Enterprises, Inc.
3030 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92513-7638
p: 800.322.8216 / www.fleetwoodrv.com

IMPORTANT RECALL INFORMATION #80324

May 2008

**TO: ALL FLEETWOOD DEALER PRINCIPALS,
SERVICE MANAGERS
AND PARTS MANAGERS**

**SUBJECT: RECALL CAMPAIGN #80324
2008 JAMBOREE SPORT AND TIOGA RANGER 25G MODEL CLASS C
MOTOR HOMES - SEAT BELT ASSEMBLY**

Fleetwood Enterprises, Inc., on behalf of its subsidiary manufacturing centers located in Riverside, California and Paxinos, Pennsylvania is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the National Traffic and Motor Vehicle Safety Act.

Fleetwood Enterprises, Inc., has decided that certain 2008 Jamboree Sport and Tioga Ranger 25G model class C motor homes with the wrap-around booth dinette option, fail to conform to the requirements of Federal Motor Vehicle Safety Standard No. 209, "Seat Belt Assemblies". A copy of the letter sent to owners is enclosed for your information.

WHAT IS THE PROBLEM?

On certain 2008 Jamboree Sport and Tioga Ranger 25G model class C motor homes affected by this recall, the seat belts at the two center seating positions located on the wrap-around booth dinette, may be too long to achieve proper adjustment. Lack of adequate seat belt protection increases the risk of personal injury in the event of an accident.

WHAT SHOULD YOU DO?

Owners of the above mentioned motor homes have been asked to contact a Fleetwood dealer to have the described defect remedied. In the event that you are contacted by a customer, please verify eligibility by referring to the serial number range listed in the enclosed Recall Service Bulletin #80324 prior to beginning the repairs.

Once repairs are completed, have the customer sign your dealership's Internal Repair Order and submit your request electronically through e-FDN, or you may also have the customer sign the Fleetwood Repair Order (form X-SR-042) and submit for reimbursement in accordance with Service Bulletin #80324. Customers will not be charged for these repairs.

If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific motor home. Fleetwood is asking our dealers to make repairs to stock units on dealer lots prior to sale or lease.

Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act) of 1966 requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

Please review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Safety Recall Campaign.

Thank you for helping Fleetwood with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your regional Fleetwood Service Center.

Sincerely,

FLEETWOOD ENTERPRISES, INC.

A handwritten signature in dark ink, appearing to read "Tina Inkrote". The signature is fluid and cursive, with the first name "Tina" being more prominent than the last name "Inkrote".

Tina Inkrote
Service Administrator
Motor Home Division

Enclosures: Recall #80324 Customer Letter
Recall #80324 Service Bulletin

Recall Bulletin 80324



**RECALL
BULLETIN:**
80324

**YEAR(S)
AFFECTED:**
2008

**PRODUCT(S)
AFFECTED:**
Jamboree Sport,
Tioga Ranger

**MODEL(S)
AFFECTED:**
25G
with
Wrap-Around
Booth Dinette
Option

SUBJECT:
Replace Two
Seat Belts in the
Wrap-Around
Booth Dinette

KEYWORDS:
Seat Belt,
Seat Belts,
Belt

ISSUE DATE:
May 2008

The purpose of this Bulletin is to inform Fleetwood dealers of the need to replace two seat belt sets in the wrap-around dinette booth on certain 2008 Jamboree Sport and Tioga Ranger motor homes with serial numbers listed in the bulletin.

CONDITION:

Fleetwood has discovered that certain 2008 Jamboree Sport and Tioga Ranger Class 'C' motor homes may have excessively long seat belts at the two center seating positions in the 25G model with the wrap-around booth dinette option. The seat belts may be too long to achieve proper adjustment.

Read this entire document before proceeding.

Verify the motor home is eligible for this Recall by referring to the affected Fleetwood serial numbers listed at the end of this Bulletin. Follow the procedures below for all affected motor homes.

INSPECTION:

1. Remove the seat cushion from the center section of the wrap-around dinette booth to provide access to the seat belt anchor locations. Measure each affected seat belt section containing a buckle. Measure from the center of the anchor bolt, at the sidewall, to the tip of the buckle. If the length is between 22 to 26 inches, no further action is required for this Bulletin and the cushion can be replaced. If the measurement length exceeds 26 inches, complete the Correction procedure. See Figure 1.




Figure 1

CORRECTION:

2. Store the cushion in a clean place for later reinstallation.
3. Note the attachment locations for each of the affected seat belt buckle sections and seat belt tongue sections. Also note the stacking order of lock washers and the seat belt anchors on each of the seat belt attachment bolts.

© 2008 Fleetwood Enterprises, Inc.

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that if you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods.

4. Remove the bolts securing the tongue and buckle seat belt sections for the two center seating locations of the dinette wrap-around booth. Retain bolts and lock washers for reassembly. Cut up and then discard the original seat belt sections.
5. Install the new seat belt sections, using original bolts and lock washers, according to the notes and stacking order from Step 3. Position the seat belt anchor brackets in-line with the seat belt pull direction. See Figure 2.
6. Torque the seat belt anchor bolts to 26 ft-lbs.
7. Replace the wrap-around dinette seat cushion.




Figure 2

PARTS:

<u>Part #</u>	<u>Description</u>	<u>Qty.</u>
551513	Kit, Seat Belts, Recall #80324 (Includes two complete seat belt sets per affected motor home)	1

TOOLS:

Tape Measure
 5/8" Socket with Extension
 Ratchet Handle
 Torque Wrench with a Minimum Capacity of 30 ft-lbs.
 Utility Knife

WARRANTY LABOR ALLOWANCE:

Use Flat Rate Codes:

Install two new seat belts, 4 segments.

9202 - 11	0.10 hr.	Inspected/Not Defective
9202 - 12	0.20 hr.	Inspected/Defective/Repaired
9202 - 17	0.10 hr.	Customer Unreachable

If you have any questions concerning the Bulletin, contact Fleetwood Dealer Technical Support at:
 (800) 816-9825

Fleetwood Service Literature is available at: www.fleetwoodrvdealers.com

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personnel safety nor vehicle safety will be jeopardized by the selected service methods."

Affected 2008 Jamboree Sport Motor Home Unit Serial Numbers:

789G84797541	789G84798592	789G84799376	789G87172307
789G84797740	789G84798651	789G84799377	789G87172308
789G84797764	789G84798652	789G84799378	789G87172601
789G84797765	789G84798721	789G84799379	789G87172602
789G84798123	789G84798722	789G84799380	789G87172603
789G84798252	789G84798723	789G84799402	789G87172756
789G84798253	789G84798724	789G84799403	789G87172757
789G84798255	789G84798840	789G84799404	789G87172758
789G84798257	789G84798841	789G84799643	789G87172850
789G84798448	789G84798842	789G84799644	789G87172851
789G84798449	789G84798843	789G84799704	789G87172852
789G84798450	789G84798844	789G84799706	789G87172853
789G84798451	789G84798949	789G87172124	789G87172854
789G84798473	789G84798963	789G87172233	789G87173050
789G84798474	789G84799156	789G87172235	789G87173051
789G84798475	789G84799157	789G87172305	
789G84798591	789G84799291	789G87172306	

Affected 2008 Tioga Ranger Motor Home Unit Serial Numbers:

788G84797533	788G84797843	788G84798444	788G84798648
788G84797534	788G84797844	788G84798445	788G84798649
788G84797535	788G84797845	788G84798446	788G84798650
788G84797536	788G84797847	788G84798447	788G84798653
788G84797537	788G84797851	788G84798476	788G84798654
788G84797538	788G84797927	788G84798477	788G84798655
788G84797539	788G84797929	788G84798588	788G84798656
788G84797707	788G84798111	788G84798589	788G84798657
788G84797709	788G84798112	788G84798590	788G84798720
788G84797711	788G84798126	788G84798608	788G84798836
788G84797742	788G84798261	788G84798609	788G84798838
788G84797744	788G84798263	788G84798610	788G84798839
788G84797745	788G84798442	788G84798611	788G84798920
788G84797763	788G84798443	788G84798612	788G84798921

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 151 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."

Affected 2008 Tioga Ranger Motor Home Unit Serial Numbers (continued):

788G84798922	788G84799370	788G84799640	788G87172378
788G84798923	788G84799372	788G84799641	788G87172611
788G84798924	788G84799373	788G84799642	788G87172612
788G84798947	788G84799374	788G84799708	788G87172613
788G84798948	788G84799375	788G87172231	788G87172614
788G84799152	788G84799405	788G87172232	788G87172753
788G84799153	788G84799406	788G87172309	788G87172754
788G84799226	788G84799407	788G87172310	788G87172755
788G84799227	788G84799604	788G87172311	788G87172899
788G84799228	788G84799605	788G87172312	788G87172900
788G84799229	788G84799606	788G87172313	788G87172901
788G84799230	788G84799607	788G87172314	788G87172903
788G84799287	788G84799608	788G87172315	788G87172904
788G84799288	788G84799637	788G87172375	788G87172905
788G84799289	788G84799638	788G87172376	788G87173052
788G84799290	788G84799639	788G87172377	788G87173053

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that, if you have received a notice of recall (a failure to comply) from Fleetwood (or any component manufacturer), you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."



Fleetwood Enterprises, Inc.
3030 Myers Street / Riverside, CA 92503-5527
P.O. Box 7638 / Riverside, CA 92513-7638
p: 800.322.8216 / www.fleetwoodrv.com

IMPORTANT RECALL INFORMATION #80324

June 2008

Dear Valued Fleetwood Motor Home Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Fleetwood Enterprises, Inc., on behalf of its subsidiary manufacturing centers located in Riverside, California and Paxinos, Pennsylvania has decided that certain 2008 Jamboree Sport and Tioga Ranger, 25G model class C motor homes with the wrap-around booth dinette option, fail to conform to the requirements of Federal Motor Vehicle Safety Standard No. 209, "Seat Belt Assemblies".

WHAT IS THE PROBLEM?

On certain 2008 Jamboree Sport and Tioga Ranger 25G model class C motor homes affected by this recall, the seat belts at the two center seating positions located on the wrap-around booth dinette, may be too long to achieve proper adjustment. Lack of adequate seat belt protection increases the risk of personal injury in the event of an accident.

WHAT SHOULD YOU DO?

Please make certain your motor home is inspected and repaired by contacting your selling dealer, and making an appointment to have this inspection and repair performed. If they are not available, another Fleetwood motor home dealer may do this work for you.

WHAT WILL FLEETWOOD DO?

With your continued satisfaction in mind, it is our intention to have these repairs made at your convenience with as little disruption as possible. Effective immediately, Fleetwood dealers will be supplied with all the information needed to enable them to inspect and if necessary, replace the two seat belts.

The total length of time your motor home will be out of service will depend on the dealer's work schedule.

If you have had this concern corrected previously, you may be eligible for reimbursement of your cost for that repair. For more information regarding this recall #80324, contact Fleetwood Owner Relations at 800-509-3418.

When you deliver your motor home for repairs, your dealer will complete a Fleetwood Repair Order. Upon completion of the repair, please sign the dealership's Repair Order or Fleetwood's Repair Order and fill out the enclosed self-addressed Vehicle Information Update Card and return it to Fleetwood. This will allow us to update our records and if necessary, notify the new owner using the information you provided.

For leased vehicles: Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If you are unable to obtain the specified repair promptly and without charge, please contact:

FLEETWOOD OWNER RELATIONS - RECALL #80324

P.O. Box 1007
Decatur, Indiana 46733
(800) 509-3418

If you believe that the dealer and Fleetwood Enterprises, Inc., have failed or have been unable to remedy the defect without charge or within a reasonable period of time, you may submit a complaint to:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

Or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to
<http://www.safercar.gov>

Fleetwood Enterprises, Inc., is taking these steps in the interest of your safety. We regret any inconvenience this may cause you.

Sincerely,

FLEETWOOD ENTERPRISES, INC.



Tina Inkrote
Service Administrator
Motor Home Division