

Recall Bulletin 80624



**RECALL
BULLETIN:**
80624

**YEAR(S)
AFFECTED:**
2008, 2009

**PRODUCT(S)
AFFECTED:**

See list of
affected serial
numbers
included with this
Bulletin

**MODEL(S)
AFFECTED:**
All

SUBJECT:
Install new
Manufacturer
Federal
Certification
Tag and
Occupant and
Cargo Carrying
Capacity Tag

KEYWORDS:
Manufacturer
Federal
Certification
Tag, Occupant
and Cargo
Carrying
Capacity Tag,
Weight Tag

ISSUE DATE:
July 2008

© 2008 Fleetwood Enterprises, Inc.

The purpose of this Bulletin is to inform Fleetwood dealers of the need to replace the Manufacturer Federal Certification Tag and the Occupant and Cargo Carrying Capacity Tag on certain 2008 and 2009 Class A and Class C motor homes.

CONDITION:

Fleetwood Enterprises, Inc., has discovered that motor homes manufactured May 19, 2008 through June 20, 2008 have an incorrect Occupant and Cargo Capacity Rating listed on the Manufacturer Federal Certification Tag and the Occupant and Cargo Carrying Capacity Tag.


Read this entire document before proceeding.

CORRECTION:

Retail owners of affected motor homes and dealers holding affected motor homes in inventory will receive a package from Fleetwood containing a new and corrected, **serial number specific**, Manufacturer Federal Certification Tag and Occupant and Cargo Carrying Capacity Tag. Verify eligibility by referring to the affected motor home serial numbers listed at the end of this Bulletin before applying new labels.

Important: Be sure the correct replacement Manufacturer Federal Certification Tag and Occupant and Cargo Carrying Capacity Tag are on-hand before proceeding.

1. Locate the original Federal Certification Tag, adhered to the wall behind the driver's seat (Class A coaches), or inside the driver's compartment (Class C coaches).
2. Record any additional weight information (if present) that was written on the original Manufacturer Federal Certification Tag due to the addition of options after the motor home was manufactured. (See Figure 1.) Transfer this information to the new Manufacturer Federal Certification Tag using a black, fine point, permanent marker.



This bulletin is supplied for technical information only and is not an authorization for repairs.


Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."

3. a) If the original Federal Certification Tag is loose or peeling, remove it and discard. Remove any adhesive residue in the application area using a clean shop cloth slightly dampened with isopropyl alcohol.
- b) If the original Federal Certification Tag is adhered securely in place, use a black permanent marker to deface it.
4. Peel and tear approximately 1" from the top of the adhesive backing of the new Federal Certification Tag. (This will allow control of the application.) Slowly apply the new Tag directly over the original, using your fingers to smooth down newly-applied areas. (If the original Tag was removed in Step 3a, apply the new Tag in the same location as the original.) Continue to remove backing, working from top to bottom, until the entire tag completely adheres to and covers the original tag.

Note: New Federal Certification labels have "tamper-proof" edges and are designed to tear if removal is attempted.

4. Locate the original Occupant and Cargo Carrying Capacity tag affixed to the inside of the entry door of the motor home. Record any additional weight information (if present) that was written on this tag due to the addition of options after the motor home was manufactured. (See Figure 2.) Transfer this information to the new Occupant and Cargo Carrying Capacity tag using a black, fine point, permanent marker. Then, remove and discard the original Occupant and Cargo Carrying Capacity tag.



5. Peel the adhesive backing from the new Occupant and Cargo Carrying Capacity Tag and carefully apply to the entry door in the same location as the original Tag. Use your fingers to smooth down newly-applied areas.

Note: It may be helpful to remove a small portion of the backing at a time in order to prevent air bubbles.

PARTS:

Use tags supplied with the Recall mailing. No additional parts are necessary.

TOOLS:

Black, Fine Point, Permanent Marker Clean Shop Cloth Isopropyl Alcohol

WARRANTY LABOR ALLOWANCE:

Use Flat Rate Codes:

Install new Federal Certification Tag and Occupant and Cargo Carrying Capacity Tag

9205 - 11	0.10 hr.	Inspected/Not Defective
9205 - 12	0.10 hr.	Inspected/Defective/Repaired
9205 - 17	0.10 hr.	Customer Unreachable

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."

If you have any questions concerning the Bulletin, contact Fleetwood Dealer Technical Support
at:
(800) 816-9825

Fleetwood Service Literature is available at: www.fleetwoodrvdealers.com

Recall 80624 Affected 2008 Unit Serial Numbers

American Eagle

719E84403463	719E84403476	719E84403511	719F84403535
719C84403468	719C84403507	719E84403513	

Bounder Diesel

735S84403500

Discovery

770X84403457	770X84403480	770R84403488	770X84403558
770X84403461	770X84403481	770R84403489	770X84403560
770X84403462	770X84403482	770R84403490	770X84403561
770X84403478	770X84403483	770R84403556	770X84403562
770X84403479	770X84403485	770R84403557	770X84403563

Excursion

779X84403494	779X84403498	779X84403548	779X84403550
779X84403497	779R84403544	779X84403549	

Expedition

730D84403501	730D84403503	730F84403541
730D84403502	730H84403504	

Pace Arrow

777P87173988	777P87173989
--------------	--------------

Providence

772X84403491

continued on next page

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."

Recall 80624 Affected 2008 Unit Serial Numbers (continued)

Revolution LE

781K84403397	781K84403405	781K84403474	781R84403523
781K84403403	781K84403472	781K84403475	781K84403527
781K84403404	781K84403473	781K84403518	

Southwind

721D84700389	721D84700598	721V84700630	721V84700648
721G84700554	721D84700599	721V84700631	721V84700649
721G84700557	721V84700624	721V84700633	721V84700651
721A84700583	721V84700625	721V84700643	721C84798558
721A84700584	721V84700626	721V84700644	721D87173997
721A84700586	721V84700627	721V84700645	721D87173998
721D84700589	721V84700629	721V84700647	721D87174030

Terra LX

791M84700326
791N84700375
791N84700380

Recall 80624 Affected 2009 Unit Serial Numbers

American Allegiance

771G94403464 771G94403469

Bounder

739H94700535	739H94700547	739E94700595	739P97173985
739H94700536	739H94700548	739E94700596	739P97173986
739H94700537	739H94700549	739P94700637	739P97173987
739H94700538	739H94700551	739W94700692	739G97173991
739H94700539	739E94700577	739P97173969	739E97174031
739H94700540	739E94700578	739H97173980	739E97174034
739H94700541	739E94700579	739H97173981	739P97174036
739H94700542	739E94700592	739E97173983	
739H94700544	739E94700593	739E97173984	

continued on next page

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."

Recall 80624 Affected 2009 Unit Serial Numbers (continued)

Fiesta LX

792N94700694	792N94700702	792N94700705	792N94700708
792N94700700	792N94700703	792N94700706	792N94700709
792N94700701	792N94700704	792N94700707	

Icon

766A94700450	766A94700528	766A94700717	766A97174006
766D94700512	766D94700662	766A94700718	766D97174008
766D94700514	766D94700663	766A94700719	766A97174022
766D94700515	766A94700716	766A97174005	766A97174023

Jamboree

751M94700433	751M94700510	751M94700668	751M97173962
751M94700507	751M94700511	751M94700669	751M97173963
751M94700508	751M94700573	751M94700670	751M97174002
751M94700509	751M94700575	751M97173961	

Jamboree GT

773W94700436

Jamboree Sport

789G94700398	789Q94700710	789B94700729	789W94700737
789G94700617	789Q94700711	789B94700730	789W94700739
789G94700618	789Q94700712	789B94700731	789G97174013
789W94700657	789Q94700713	789B94700732	

Pulse

765D94700461	765D94700520	765D94700658	765A94700725
765D94700462	765D94700521	765D94700659	765A94700727
765D94700465	765A94700529	765D94700660	765A97173955
765D94700516	765A94700530	765D94700661	765A97173957
765D94700517	765A94700531	765A94700721	765A97173959
765D94700518	765A94700532	765A94700723	
765D94700519	765A94700533	765A94700724	

continued on next page

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that:
If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."

Recall 80624 Affected 2009 Unit Serial Numbers (continued)

Terra LX

791N94700695

Tioga

741M94700429	741M94700525	741M94700664	741M94700767
741M94700522	741M94700526	741M94700665	741M97173964
741M94700523	741M94700569	741M94700666	741M97174025
741M94700524	741M94700570	741M94700667	

Tioga Ranger

788G94700563	788G94700613	788B94700673	788W94700740
788Q94700601	788G94700614	788B94700674	788G94700771
788Q94700602	788G94700615	788B94700675	788G94700772
788G94700607	788G94700616	788B94700676	788G94700773
788G94700608	788W94700619	788B94700677	788G97174018
788G94700609	788W94700620	788B94700678	788G97174019
788G94700610	788W94700621	788B94700679	788W97174020
788G94700611	788W94700622	788Q94700715	
788G94700612	788W94700623	788B94700733	

This bulletin is supplied for technical information only and is not an authorization for repairs.

Federal Law (Section 154 of the National Traffic and Motor Vehicle Safety Act of 1966) requires that: If you have received a notice of recall or failure to comply from Fleetwood or any component manufacturer, you must repair or otherwise correct the defects on vehicles remaining in your inventory, according to the notification, before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.

"It is impossible to know, evaluate and advise the service trade of all conceivable ways in which service might be done or of the possible hazardous consequences of each way. Accordingly, anyone who uses a service procedure or tool must first assure that neither personal safety nor vehicle safety will be jeopardized by the selected service methods."