

1200 New Jersey Avenue SE Washington, DC 20590

April 17, 2009

ROBERT BABCOCK SENIOR MANAGER, REGULATIONS AND CERTIFICATION DEPARTMENT HYUNDAI-KIA AMERICA TECHNICAL CENTER, INC. 6800 GEDDES ROAD SUPERIOR TOWNSHIP MI 48197

NVS-215dgl 09V-122

SUBJECT: STOP LAMP SWITCH ASSEMBLY

DEAR MR. BABCOCK:

This letter serves to acknowledge Hyundai-Kia America Technical Center, Inc's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the products described below for which a safety recall campaign shall be conducted pursuant to Federal law.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

HYUNDAI/ACCENT/2006-2007 HYUNDAI/AZERA/2007 HYUNDAI/ELANTRA/2007 HYUNDAI/ENTOURAGE/2006-2007 HYUNDAI/SANTA FE/2007 HYUNDAI/SONATA/2006-2007 HYUNDAI/TUCSON/2005-2007 HYUNDAI/VERACRUZ/2007-2008

NHTSA Campaign Number: 09V-122

Mfg's Report Date: April 14, 2009

Components: SERVICE BRAKES, HYDRAULIC: SWITCHES: BRAKE LIGHT

Potential Number of Units Affected: 531,894

Summary:

HYUNDAI IS RECALLING 531,894 MY 2006-2007 ACCENT, ENTOURAGE, SONATA, MY 2007 AZERA, ELANTRA AND SANTA FE, MY 2005-2007 TUCSON AND MY 2007-2008 VERACRUZ VEHICLES. THE STOP LAMP SWITCH IN THE AFFECTED VEHICLES MAY MALFUNCTION. A MALFUNCTIONING STOP LAMP SWITCH MAY CAUSE THE BRAKE LIGHTS TO NOT ILLUMINATE WHEN THE BRAKE PEDAL IS DEPRESSED OR MAY CAUSE THE BRAKE LIGHTS TO REMAIN ILLUMINATED WHEN THE BRAKE PEDAL IS RELEASED. A STOP LAMP SWITCH MALFUNCTION MAY AFFECT THE OPERATION OF THE BRAKE-TRANSMISSION SHIFT INTERLOCK FEATURE SO THE TRANSMISSION SHIFTER WOULD NOT BE ABLE TO BE SHIFTED OUT OF PARK POSITION. IT MAY ALSO CAUSE THE ELECTRONIC STABILITY CONTROL (ESC) MALFUNCTION LIGHT TO ILLUMINATE, AND IT MAY NOT DEACTIVATE THE CRUISE CONTROL WHEN THE BRAKE PEDAL IS DEPRESSED.

Consequence:

THESE MALFUNCTIONS MY LEAD TO A CRASH.

Remedy:

DEALERS WILL REPLACE THE STOP LAMP SWITCH FREE OF CHARGE. THE RECALL IS EXPECTED TO BEGIN DURING APRIL 2009. OWNERS MAY CONTACT HYUNDAI CUSTOMER ASSISTANCE CENTER AT 1-800-633-5151.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO <u>HTTP://WWW.SAFERCAR.GOV</u>.

This recall was the subject of a Preliminary Evaluation, PE09-003, conducted by the Office of Defects Investigation.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

We have reviewed your proposed owner letter and it meets the requirements of 49 CFR Part 577.

Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contacts for this recall will be Delia Lopez who may be reached by phone at 202-366-9525, or by email at <u>Delia.lopez@dot.gov</u>, or through the office email at <u>RMD.ODI@dot.gov</u>. We look forward to working with you for successful completion of this recall campaign.

Sincerely,

George H. Person Chief, Recall Management Division Office of Defects Investigation Enforcement