



August 13, 2009

MR. JAN URBAHN
GENERAL MANAGER, SAFETY ENGINEERING
AND INTELLIGENT TRANSPORTATION SYSTEMS
BMW OF NORTH AMERICA, LLC
PO BOX 1227
WESTWOOD, NJ 07675-1227

NVS-215kjs 09V-327

SUBJECT: SAFETY BELT TENSIONERS

DEAR MR. URBAHN:

This letter serves to acknowledge BMW of North America LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety defect in the vehicles described below for which a safety recall campaign will be conducted pursuant to Federal law.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/Z4/2009

NHTSA Campaign Number: 09V-327 Mfg's Report Date: August 11, 2009

Components: ELECTRICAL SYSTEM:WIRING

Potential Number of Units Affected: To be provided

Summary:

BMW IS RECALLING CERTAIN MODEL YEAR 2009 Z4 30I AND 35I VEHICLES MANUFACTURED BETWEEN MARCH 10 AND MARCH 19, 2009. A DEFECTIVE CRIMP CONNECTOR IN A BELT TENSIONER WIRING PLUG MAY LEAD TO INCREASED ELECTRICAL RESISTANCE OF THAT CONNECTION.

Consequence:

INCREASED ELECTRICAL RESISTANCE IN THAT CIRCUIT COULD CAUSE THE SAFETY BELT TENSIONER TO FAIL TO DEPLOY IN A CRASH, POSSIBLY RESULTING IN INCREASED INJURY TO THE SEAT OCCUPANT.

Remedy:

THE MANUFACTURER HAS NOT YET PROVIDED THE AGENCY WITH A REMEDY OR NOTIFICATION SCHEDULE. OWNERS MAY CONTACT BMW AT 1-800-831-1117.

Notes:

CUSTOMERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO http://www.safercar.gov.

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

Please provide the following additional information and be reminded of the following requirements:

Please provide us with the quantity of vehicles involved for this recall.

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on or before 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at 202-366-5227, or by email at kelly.schuler@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you toward a successful completion of this recall campaign. Sincerely,

George H. Person

Chief, Recall Management Division

Office of Defects Investigation

Enforcement