



TRUCKS
Nissan Diesel America, Inc.

Date: May 4, 2009
To: Dealer Principal
Dealer Service Manager
From: Service Operations Department
Re: Notification Letter for Voluntary Safety Recall Campaign # 09V-111

Nissan Diesel America, Inc. has determined that specific 2008 Model Year UD3300 model vehicles equipped with the Arvin Meritor 2-Speed rear axle do not meet the Federal Motor Vehicle Safety Standard (FMVSS) 121 "Air Brake Systems" regulation.

The length of the air brake hose installed between the relay valve and quick release valve for the left rear air brake assembly is incorrect and may increase the resistance in the air supply. Incorrect length of the air brake hose will increase the risk of a crash without prior warning. As a remedy, the air brake hose will be replaced.

Dealers are requested to proceed immediately to make the necessary repair to the affected vehicles in inventory. **It is a violation of federal law for a dealer to deliver a new or used motor vehicle covered by a recall notice until the recall remedy has been performed.** Owners of affected vehicles will receive an "Authorization for Recall Notification Service" card. This postage pre-paid card must be filled out correctly and returned to the address on the card indicating whether the vehicle was repaired, transferred, sold, etc. (refer to the UD Warranty Policies & Procedures Manual, Part III, Section 1). For vehicles without an "Authorization for Recall Service" card, check the vehicle identification number with the Vehicle Service Notification screen of the NDAINET Warranty Claim System menu.

Dealers will need to contact NDA Service Operations with the VIN of the involved vehicle to order the replacement brake hose required to complete this recall. NDA will then ship the required replacement brake hose to the dealer at no charge via overnight Federal Express. **Contact Michael Ricks at 972-756-5532 or mricks@nissandiesel.com.**

Federal regulations require that all vehicle lessors must notify all lessees within ten (10) days of receiving this notice.

Repairs to correct this condition consist of replacing the brake hose. We estimate that approximately 4 hours will be required to complete the repairs. After the repairs have been performed, please return the postage prepaid "AUTHORIZATION FOR RECALL SERVICE" card to Nissan Diesel America, Inc. Service Operations Department.

All owners of affected vehicles will be notified by mail to schedule an appointment with an authorized UD Truck Dealer to have this safety recall performed free of charge.

Please find the following information enclosed with this letter:

- Recall Bulletin # 09V-111 dated May 4, 2009.
- Customer Notification Letter dated May 4, 2009.
- Excel Worksheet with involved VIN's and locations.

Complete details and procedures for this safety recall may be found in Recall Bulletin # 09V-111 issued with this letter. Recall Bulletin # 09V-111 is also posted on the Service website of the NDAINET and additional copies of the bulletin are available upon request. Any questions concerning this safety recall may be directed to the Technical Support Manager or any of the Service Operations staff at Nissan Diesel America, Inc.

C O R P O R A T E O F F I C E

P.O. Box 152034, Irving, Texas 75015-2034 • 5930 West Campus Circle Drive, Irving, Texas 75063
Telephone 972-756-5500 • Fax 972-550-1255
<http://www.udtrucks.com>