

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS3959  
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 11, 2016

Subject: 09047C – Safety Recall  
Engine Compartment Fire  
Revised Warranty Transaction Section and Service Procedure

Models: 1997-2003 Buick Regal  
2000-2003 Chevrolet Impala  
1998-1999 Chevrolet Lumina  
1998-2003 Chevrolet Monte Carlo  
1998-1999 Oldsmobile Intrigue  
1997-2003 Pontiac Grand Prix  
Equipped with 3.8L V6 engine a 3.8L V6 Naturally Aspirated Engine  
(RPO L36 - VIN K)

To: All General Motors Dealers

The Warranty Transaction section and Service Procedure in this bulletin have been revised to provide service repair tips that may reduce the amount of time and effort required to perform the repair. In addition, beauty cover removal, retention, and disposal information is provided. Please discard all copies of bulletin 09047B.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS