

GM CUSTOMER CARE AND AFTERSALES

DCS2406

URGENT - DISTRIBUTE IMMEDIATELY

Date: May 18, 2010

Subject: 07035A – Safety Recall
Engine Compartment Fire
Revised Service Procedure

Models: 1997-2003 Buick Regal GS, Pontiac Grand Prix GTP
Equipped with 3.8L V6 Supercharged Engine (L67 – VIN
1)

To: All GM Dealers (excluding Saturn and HUMMER)

Attention: General Manager, Service Manager, Parts Manager,
Used Car Vehicle Manager, and Warranty Administrator

The Service Procedure in bulletin 07035A has been revised. Technicians should review the revised service procedure immediately.

Please discard all copies of bulletin 07035, issued April 2008.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.