

GM CUSTOMER CARE AND AFTERSALES

DCS2421

URGENT - DISTRIBUTE IMMEDIATELY

Date: June 22, 2010

Subject: 09199A – Safety Recall
Loss of Power Brake Assist in Extreme Cold Weather
Revised Service Procedure

Models: 2009-2010 Pontiac Vibe Equipped with 1.8L Engine and
Registered in Certain States

To: All GM Dealers (except Saturn, HUMMER)

Attention: General Manager, Service Manager, Parts Manager,
New Car Vehicle Manager, Used Car Vehicle Manager,
and Warranty Administrator

The service procedure in bulletin 09199A has been revised to include a statement to ensure the air intake connector is properly aligned with the throttle body to prevent a whistling noise during light throttle application.

Please discard all copies of bulletin 09199, issued October 1999.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.