

Axle Change Safety Recall Work Instructions Denali[®], NorthShore[®]

Dear Dealer:

On the vehicles subject to this recall, the incorrect axles were installed during the manufacturing process. Axles rated at 4,400 lbs. were installed on these vehicles when axles rated at 5,080 lbs. should have been installed.

Required Parts

Qty 2 5200 # Axles (Order from Dutchmen part # 103519)

What You Should Do

- Replace the existing axles with the 5200# axles
- This job has a total repair allowance of 2 of the dealer's posted labor hours. To collect the allowance submit the claim to Dutchmen using job code number: 640000049

If you have questions concerning this recall please contact the **Dutchmen Warranty/Service Department** by mail at Dutchmen Manufacturing Inc., P.O. Box 2164, Goshen, IN 46527, by email at warranty@dutchmen.com, or by phone at 574-537-0700.

Sincerely,



Kelly Green
Director of Parts, Service, and Warranty