

May 2009

# 2010 Mazda3 Emission Harness Voluntary Safety Recall 5409D

Dear Mazda Owner:

This notice is sent to you in accordance with the requirements of the National Highway Traffic and Motor Vehicle Safety Act.

Mazda Motor Corporation has decided that a defect which relates to motor vehicle safety exists in certain 2010 Mazda3 vehicles produced from October 7, 2008 through April 10, 2009. If you are a recipient of this notice, your vehicle is included in this recall.

## What is the problem?

On certain 2010 Mazda3 vehicles, the clearance between the emission harness and the housing of the starter motor may be insufficient. Due to this, the covering of the harness may be damaged from vibration during operation possible resulting in a short-circuit between certain harness wires and the starter housing. This condition could cause an engine control malfunction and/or poor shift quality. In the worst case, the main fuse may blow out, causing the engine to stall and an inability to restart, increasing the risk of a crash.

#### What will Mazda do?

Your Mazda dealer will install a protector clip on the emission harness, and if necessary, repair the harness **free of charge**. The repair may take approx. half an hour to complete; however, it may take longer depending on the necessary repair and service workload at your Mazda dealership.

As a reminder, Mazda may provide alternate transportation when your vehicle is at an authorized Mazda dealership for a warranty repair. To be eligible for alternate transportation, your vehicle must be within the mileage and time limitations under the Mazda New Vehicle Limited Warranty or Powertrain Limited Warranty for 2007 and newer model years, and adhere to the Rental Car Reimbursement policy. Ask your dealer for details about the Mazda Rental Car Reimbursement Program.

#### What should you do?

Mazda is concerned about your safety, and we encourage you to make an appointment with any authorized Mazda dealer to have the emission harness repaired as soon as possible. You do not need to bring this notice to the dealer, but it may assist in the check-in process.

# What if you already paid for emission harness repair?

If you have already paid for the inspection, repair or replacement of the emission harness due to a short-circuit on the harness wire prior to receiving this notice, you may be eligible for reimbursement of reasonable repair expenses based on Mazda's repair standards.

Please complete the enclosed "Reimbursement Application Form", include the necessary documentation, and mail it to us in the pre-addressed envelope provided, allowing 6-8 weeks for processing.

## Where is the closest Mazda dealer?

To locate your nearest Mazda dealer, visit our web site and try our "Locate a Dealer" feature at <a href="https://www.MazdaUSA.com">www.MazdaUSA.com</a> or consult your local yellow pages.

## Moved or no longer own this vehicle?

If you have moved or no longer own your Mazda vehicle, please complete the enclosed prepaid *Information Change Card* as soon as possible. This enables us to update our records and notify the current owner.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

## Still have questions?

If you have any questions regarding this campaign, please contact our Customer Assistance Center at (800) 222-5500, option #6.

If Mazda or its dealers do not repair the defect free of charge and within a reasonable amount of time, you may notify the Administrator of the National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

We actively work to improve our products and search for solutions to improve your ownership experience. Please accept our apologies for any inconvenience this recall may have caused you.

Sincerely,

Mazda North American Operations

#### REIMBURSEMENT PLAN

## **Requirements for Reimbursement**

If you meet all of the following requirements, you are eligible to receive reimbursement under this plan:

- 1. An authorized Mazda dealer has inspected your vehicle and completed the 2010 Mazda3 Emission Harness Voluntary Safety Recall 5409D.
- 2. You own or have owned a 2010 Mazda3 vehicles built between October 7, 2008 and April 10, 2009.
- 3. You have paid for the inspection, repair or replacement of the emission harness due to a short-circuit on the harness wire.
- 4. You have an original or legible copy of the paid repair order or invoice receipt showing:
  - Description of the concern reported
  - Inspection, repair or replacement of the emission harness
  - Itemized part(s) and labor charges
  - Vehicle model and year, and vehicle identification number (VIN)
  - Repair date (must be prior to the launch of this campaign)
  - Repair mileage
  - Name, address, and telephone number of the authorized Mazda Dealer or a licensed repair shop where such repairs were performed
  - · Your name and address at the time of repair
- 5. Mail this reimbursement application form in the enclosed envelope to:

Mazda North American Operations Attn: Recall Reimbursement Dept P.O. Box 57085 Irvine CA 92619-7085

## **Procedure for Reimbursement Request**

Once your vehicle has had the emission harness inspected, repaired or replaced by an authorized Mazda dealer due to a short-circuit on the harness wire, you may apply for reimbursement by doing the following:

- 1. Complete the Reimbursement Application Form found on the reverse side of this page.
- 2. Mail the Reimbursement Application Form with a <u>legible</u> copy of the paid repair order and/or invoice using the enclosed envelope.
- 3. Retain copies of the paid repair order or invoice and this application form for your records.

If you wish to correspond with Mazda regarding this reimbursement plan, please write to the above address and refer to your vehicle identification number (VIN).

Any reimbursement application form that is incomplete, illegible, or sent without the legible copy of the paid repair order or invoice will be returned for completion. If Mazda has any questions concerning your application for reimbursement, you may be contacted. Please allow 6-8 weeks for processing.

## REIMBURSEMENT APPLICATION FORM

# 2010 Mazda3 Emission Harness Voluntary Safety Recall 5409D

	(Please type or print)				1	
	Name:		1			
		First	Middle	Last	-	
	Address:					
	Street Address					
			1			
		City	State	Zip Code	_	
		·				
	Phone Number:	Home:	·		_	
	none namber.	Work:				
					_	
	Vehicle Identification Number (VIN):					
	(17 digits in length)					
	Total Amount of Reimbursement Requested:  Dollars  Cents					
				Dollars Cents		
	<u>.                                    </u>					
INSTRUCTIONS FOR GENERAL RELEASE DESCRIBED BELOW:						
	Please read thoroughly     Fill in vehicle identification number					
	Sign the General Release (below)					
		Gene	ral Relea	se		
replacement	ng to Mazda Motor of emission harnes number (VIN) is:	Corporation ("Mazda") as performed to date in c	a claim for reir onnection witl	nbursement for all inspection, re n a short-circuit on the harness v	pair or vire. The vehicle	
	VIN:					
all claims fo North Ameri heir respec	for Mazda's payr r such inspection can Operations, i tive directors, off	nent of that claim, I her /repair costs. This releats ts regions/distributors	eby release l ase shall ber (foreign and es, divisions,	Mazda, its agents, and its relat refit Mazda and its authorized a domestic), its authorized deal subsidiaries, and affiliated co	agent Mazda erships, and all	
	Dated:	Sign	ned:	· · · · · · · · · · · · · · · · · · ·		