OWNER NOTIFICATION

Dear Nissan Rogue Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Nissan has decided that a defect which relates to motor vehicle safety exists in certain 2008-2009 Model Year Nissan Rogue vehicles. Our records indicate that you own or lease one of the potentially affected vehicles.

Reason for Recall

On some of the affected vehicles, the steering gear housing cover screw may have been manufactured incorrectly. Over time, the screw may gradually loosen. If this occurs, you may notice extra looseness in the steering and slower response to inputs. If this condition is ignored, the screw may eventually come out of the steering gear cover completely. If this happens, it could result in a loss of steering control and could lead to a crash.

In addition to the above defect, the material used in the nut on your Rogue that secures the Tire Pressure Monitoring System (TPMS) sensor to the wheel may corrode and potentially crack if driven regularly in areas with heavy concentrations of road salt used in winter. If this occurs, the nut may come out of the sensor causing the TPMS lamp to illuminate. If the TPMS lamp is disregarded and the vehicle continues to be driven in this condition, the tire will quickly lose air pressure resulting in a flat tire.

Below are States that regularly use road salt in the winter:

Connecticut	Maine	Missouri	Pennsylvania
Delaware	Maryland	New Hampshire	Rhode Island
District of Columbia	Massachusetts	New Jersey	Vermont
Illinois	Michigan	New York	West Virginia
Indiana	Minnesota	Ohio	Wisconsin
Iowa			

According to our records, your vehicle is currently registered in one of these States and is also subject to this safety recall campaign in addition to the one mentioned above.

What Nissan Will Do

Your Nissan dealer will inspect whether the steering gear cover screw is loose. If it is loose, it will be retightened to the proper specification. The dealer will install a cover plate to prevent the screw from coming out of the steering gear.

In addition to the aforementioned remedy, Your Nissan dealer will replace the TPMS nuts on your vehicles with new, more corrosion resistant ones.

Both of these services, free of charge for parts and labor, should take about 2 hours to complete, but your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule.

What You Should Do

Contact your Nissan dealer at your earliest convenience in order to arrange an appointment to have your vehicle repaired. Please bring this notice with you when you keep your service appointment. Instructions have been sent to your Nissan dealer. **If your steering has**

DRAFT

noticeable looseness and you believe it is slower to respond to inputs, we strongly urge you to take your vehicle to your Nissan dealer for immediate repairs.

If the dealer fails, or is unable to make the necessary repairs free of charge, you may contact the National Consumer Affairs Department, Nissan North America, Inc., P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-NISSAN1 (1-800-647-7261). You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.