



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

March 30, 2010

MR. KENNETH M. BUSH
ASSOCIATE DIRECTOR
GOVERNMENT RELATIONS
AMERICAN SUZUKI MOTOR CORPORATION
PO BOX 1100
BREA, CA 92822-1100

NVS-215dgl
10V-118

SUBJECT: AIR BAG & STEERING COLUMN FASTENERS

DEAR MR. BUSH:

This letter serves to acknowledge American Suzuki Motor Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a defect in the vehicles listed below for which a safety recall campaign will be conducted pursuant to Federal law.

Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
SUZUKI/EQUATOR/2010

NHTSA Campaign Number: 10V-118

Mfg's Report Date: March 23, 2009

Components: STEERING: GEAR BOX: SHAFT SECTOR
AIR BAGS: FRONTAL: SENSOR/CONTROL MODULE

Potential Number of Units Affected: 15

Summary:

SUZUKI HAS NOTIFIED NHTSA OF A DEFECT IN CERTAIN MODEL YEAR 2010 EQUATOR TRUCKS MANUFACTURED FROM FEBRUARY 22, 2010 TO MARCH 13, 2010. THE FASTENERS SECURING THE PASSENGER FRONT AIR BAG MODULE, AND ALSO THE FASTENERS SECURING THE STEERING SHAFT POSITIONING BRACKET MAY NOT HAVE BEEN TIGHTENED TO THE PROPER TORQUE SPECIFICATION.

Consequence:

IN THE EVENT OF A CRASH, THE PASSENGER FRONT AIR BAG DEPLOYMENT TRAJECTORY MIGHT BE AFFECTED. THE FASTENERS COULD POSSIBLY COME OUT OF THE STEERING COLUMN POSITIONING BRACKET INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL INSPECT THE STEERING COLUMN AND THE PASSENGER FRONT AIR BAG FASTENERS AND ANY MISSING FASTENERS WILL BE REPLACED AND ALL LOOSE FASTENERS WILL BE RETIGHTENED TO THE PROPER TORQUE SPECIFICATIONS FREE OF CHARGE. THE MANUFACTURER HAS NOT YET PROVIDED AN OWNER NOTIFICATION SCHEDULE. OWNERS MAY CONTACT SUZUKI AT 1-800-934-0934.

Notes:

CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

The information in your defect report appears to satisfy the requirements of 49 CFR 573.6.

Please provide the following additional information and be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within 30 days after the close of the calendar quarter in which the campaign was initiated. Thereafter, quarterly reports will be due on or before 30 days after close of the calendar quarter.

Your contact for this recall will be Delia Lopez who may be reached by phone at 202-366-9525, or by email at Delia.lopez@dot.gov, or through the office email at RMD.ODI@dot.gov. We look forward to working with you toward a successful completion of this recall campaign.

Sincerely,

A handwritten signature in black ink, appearing to read 'G. Person', with a long horizontal flourish extending to the right.

George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement