

RECEIVED

By Recall Mgt Div. at 2:15 pm, Apr 30, 2010

10V-178
(4 pages)

DAIMLER

Daimler Trucks North America
Nasser Zamani
Senior Manager
Compliance and Regulatory Affairs

April 29, 2010

Dan Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attention: Recall Management Division (NVS-215)
1200 New Jersey Avenue S.E.
Washington D.C. 20590

Re: Defect Information Report FL-577, Stop Lamps (Amendment)

Mr. Smith

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith reports a safety campaign to recall approximately 6669 Thomas Built Buses Saf-T-Liner C2 school bus vehicles and 6,569 Freightliner Business Class M2 and Freightliner Custom Chassis Corporation S2 chassis and MC chassis manufactured January 2005 through April 2010, and equipped with hydraulic brakes with a defect that may cause the stop lamps in some vehicles to be intermittent during light brake applications.

Per a request from ODI, the school bus and Non-school bus populations have been separated into two DIRs. Attached are the corrected Daimler Trucks North America's Defect Information Reports.

Please contact me if you have any questions.

Sincerely yours,



Nasser Zamani

Cc: Michael Mason, CAL-OSHA
Enclosure
Certified Mail# 7006 3450 0000 3866 7904

A Daimler Company

Daimler Trucks North America LLC
4747 N. Channel Avenue
Portland OR 97217-7699
503-745-6910 Phone
503-745-5544 Fax
Nasser.Zamani@Daimler.com

DAIMLER

Defect Information Report (Section 573.6)

Date: April 21, 2010

(c)(1) **Manufacturer:** Daimler Trucks North America LLC
P.O. BOX 3849
Portland, Oregon 97208
(503) 745-5219

Brands: Freightliner, Freightliner Custom Chassis Corporation

(c)(2) **Vehicles identification:**

Model(s) affected: Freightliner Business Class M2
FCCC B2 chassis, S2 chassis, MC chassis

Model Years affected: 2005, 2006, 2007, 2008, 2009, 2010, 2011

Manufacture Dates: January 19, 2005 through April 16, 2010

Basis for determining population: All vehicle models listed above and built January 2005 through April 2010 with hydraulic brakes

Component manufacturer if other than the vehicle manufacturer: N/A

(c)(3) **Total number of vehicles potentially affected:** Approximately 6,569

(c)(4) **Percentage of vehicles estimated to contain the defect:** 2%

(c)(5) **Description of the defect:** The stop lamps may be intermittent during light brake applications.

49CFR Section 577.5(f) Evaluation of the risk to motor vehicle safety: The stop lamps may not properly indicate that the service brakes are applied which may lead to a crash without prior warning.

(c)(6) **Chronology of principal events:**

2/3/2010 – NHTSA opened a PE to investigate allegations of brake lights not illuminating during a “light brake pedal application” on Model Years (MY) 2009 through 2011 Thomas Built Saf-T-Liner C2 model school buses.

DTNA reviewed warranty data and found 296 claims (USA + Canada populations) related to brake lights not illuminating on trucks and buses with hydraulic brakes produced from January 2005 to present.

DTNA reviewed customer complaint data and found 7 reports (USA + Canada population) related to the brake lights not illuminating on trucks and buses with hydraulic brakes produced from January 2005 to present.

(c)(7) **Noncompliance-test or other data:** N/A

(c)(8) **(I) Remedial program:** The remedy is unknown at this time. Repairs will be performed by Daimler Trucks North America dealerships and Direct Warranty customers, i.e., customers approved by Daimler Trucks North America to do their own warranty repairs
Reimbursement Plan: Copies will be submitted as a supplemental report when available.

DAIMLER

(ii) Estimated Owner and Dealer Notification Date: Customer notification will be by first class mail using Daimler Trucks North America records to determine the customers affected. The completion date is: TBD
Dealer notification is: TBD

(c)(9) Information for tire recalls: Not Applicable

(c)(10) Communications sent to manufacturers, dealers and owners: Copies will be submitted as a supplemental report when available.

(c)(11) Manufacturer's campaign number: FL-577