

**Automobili Lamborghini S.p.A.**10V-215
(3 Pages)

Kathleen DeMeter, Director,
Office of Defect Investigations
National Highway Traffic Safety Administration
Department of Transportation
1200 New Jersey Ave SE
Washington DC 20590

**Automobili
Lamborghini S.p.A.**Vs. riferimento
Vs. data
Oggetto
Data**Subject: Part 573 Notice of Automobili Lamborghini SpA Determination of Defect**Via Modena, 12
I-40019 Sant'Agata
Bolognese
Telefono +39 051-681 76 11
Telefax +39 051-681 76 44

This information is submitted in accordance with the requirements of Part 573 of Title 49 of the Code of Federal Regulations (49 CFR 573).

573.6 (c)(1)

Manufacturer's Name

Full corporate name Automobili Lamborghini S.p.A.

The recalled vehicle

is imported;

Designated agent:Lance Tunick
PO box 23078 Santa Fe NM87502.**Corporate official
to be contacted**Name: Rene Sueltzner,
Title: Head of Customer Service and
Spare Parts Of
Automobili Lamborghini America
LLC
Phone +1-310-664-4951
Fax +1-310-664-4975
Email rene.sueltzner@lamborghini.comCapitale Sociale
€ 50.000.000
R.E.A. Bologna 399097
Codice Fiscale 01930291206
Partita I.V.A 01930291206
A socio unico
Società del Gruppo Audi



573.6 (c)(2)

Identification of Vehicles

Make: Lamborghini

Line: Murcièlago (version LP640)
Murcièlago Roadster (version LP640)

Model Year: 2007, 2008

Month/Year of manufacture: Beginning May 2006
Ending April 2008

VIN Numbers of Affected Vehicles: Beginning ZHWBU37M57LA02062
Ending ZHWBU37S78LA03231

573.6 (c)(3)

Number of vehicles Potentially Containing the Defect

Approximately 428 vehicles are affected by this recall in the United States.

573.6 (c)(4)

Percentage of Vehicles Actually Containing Defect

Lamborghini is unable to estimate the percentage of vehicles in the United States that are potentially subject to this defect.

573.6 (c)(5)

Description of Defect

In rare cases, stress generated by the back and forth movement of gasoline inside the fuel tank during lateral and longitudinal accelerations, accompanied by vertical vibration could cause detachment of one or more spot welds holding the fuel pump support inside the fuel tank. A slow fuel leak could develop at the detached spot weld which could potentially result in a fire only if an external ignition source is present.

573.6 (c)(6)

Basis for Determination

In the course of continuous product monitoring and internal tests, Automobili Lamborghini S.p.A. has determined that in rare cases one or more spot welds holding the fuel pump support inside the fuel tank could detach potentially causing a slow fuel leak. There have been no fires, no accidents, no injuries.

Date of determination: May 11 2010

573.6 (c)(7)

Non-compliance Test Result

Not applicable

573.6 (c)(8)

Proposed Remedial Program

The Lamborghini dealers will exchange the fuel tank free of charge to customers.

Lamborghini plans to notify all owners of affected vehicles and will instruct these owners to arrange an appointment with an authorized dealer.

Pending parts availability, mailing dates are anticipated as follows:

Dealer: on or about May 21 2010
Owner: on or about May 24 2010



- 573.6 (c)(10) **Submission of communications**
Drafts are attached
- 573.6 (c)(11) **Proposed Owner Letter**
Draft is attached
- 573.6 (c)(12) **Manufacturer's Recall Code**
Lamborghini has assigned the following code:
L824-R.01.10 Murcièlago
L825-R.01.10 Murcièlago Roadster

In case of questions please contact:

Name	Alessandro Farneschi
Title	Product & Market Manager
Telephone	+39 051 6817652
Fax	+39 051 6817709
Email	alessandro.farneschi@lamborghini.com

Yours sincerely,

Automobili Lamborghini S.p.A.

A handwritten signature in black ink, appearing to be "MR" followed by a long horizontal stroke.

Maurizio Reggiani
Research and Development Director

A handwritten signature in black ink, appearing to be "A.F." followed by a long horizontal stroke.

Alessandro Farneschi
Customer Service and Spare Parts
Product and Market Manager