



Fleetwood RV, Inc.
1010 Commerce Dr.
Decatur, Indiana 46733
P: (800) 322-8216 / www.fleetwoodrv.com

November 10, 2010

Mr. Daniel C. Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Ave, SE
Washington, DC 20590

Re: Noncompliance Report

Dear Mr. Smith:

On November 5, 2010, Fleetwood RV, Inc., determined that a noncompliance of FMVSS 108, Paragraph S7.5, exists in certain motor homes as listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

The following is the information required by 49 CFR Part 573:

- This report was prepared on November 10, 2010.
 - Fleetwood RV has assigned 101105FRV as an identification code to this recall.
- (1) The affected motor homes were manufactured by the following wholly owned subsidiaries of Fleetwood RV, Inc.

Fleetwood RV, Inc. #44
1031 U.S. 224 E
Decatur, Indiana 46733

The agency should contact the following individual with respect to this recall:

Craig Biazio
National Warranty Manager
Fleetwood RV, Inc.
1010 Commerce Dr., P.O. Box 1007
Decatur, Indiana 46733
Telephone: 260-724-5960
E-mail: craig.biazio@fleetwoodrv.com

The vehicles involved in the recall are certain model year 2011 Terra Class A motor homes. These motor homes are identified, non-consecutively, as:

Terra 783DB4405800 though 783TB4407086
Manufactured 6/24/2010 through 10/4/2010

- (3) Fleetwood RV reports approximately 84 as the number of model year 2011 Terra Class A motor homes with the noncompliance.
- (4) Fleetwood RV estimates that 100% of the affected model year 2011 Terra Class A motor homes contain the noncompliance.

- (5) On motor homes affected by this recall, the high beam and low beam headlights are not in the correct positions as specified by FMVSS 108.

According to the pertinent language of FMVSS108, the lower beam should be provided by the "outboard light source (or the uppermost if arranged vertically)", and the upper beam should be provided by "the inboard light source (or the lower one if arranged vertically)".

- (6) Not applicable.

- (7) Fleetwood RV began an investigation in August 2010 when it was identified at our production facility.

Fleetwood RV is not aware of any accidents or injuries which have resulted from this noncompliance.

- (8) Fleetwood dealers will remove the existing high-beam and low-beam headlights and replace them with different low-beam and high-beam headlights in order to comply with the applicable standards of FMVSS108.

- (9) Fleetwood RV intends to conduct a dealer notification by e-mail in November 2010.

Fleetwood RV intends to conduct a customer notification in November 2010.

Fleetwood RV does not foresee any problems with implementing this voluntary recall campaign.

- (10) Copies of subsequent correspondence will be submitted to the NHTSA within five (5) working days of distribution. This correspondence will include:

- I) Letter of dealer notification
- II) Letter of customer notification
- III) Service Bulletin

A draft of these documents will be forthcoming for your review. If additional information is required, please contact Joyce Geels who can be reached by phone at (260) 724-5795 or by e-mail at joyce.geels@fleetwoodrv.com.

Sincerely,



Craig S. Biazio
National Warranty Manager