

# Part 573 Safety Recall Report

# 10E-045

**Manufacturer Name :** Bentley Motors, Inc.

**Submission Date :** SEP 12, 2024

**NHTSA Recall No. :** 10E-045

**Manufacturer Recall No. :** RE10/05



## Manufacturer Information :

## Population :

**Manufacturer Name :** Bentley Motors, Inc.

**Number of potentially involved :** 12

**Address :** 2200 Ferdinand Porsche Drive  
Herndon VA 20171

**Estimated percentage with defect :** 100 %

**Company phone :** 1-800-777-6923

## Equipment Information :

**Brand / Trade 1 :** BENTLEY

**Model :** T Series

**Part No. :** RH14071

**Size :** NR

**Function :** NR

**Descriptive Information :** BENTLEY IS RECALLING CERTAIN SERVICE BRAKE HOSES, PART NUMBER RH14071, SOLD FOR USE AS REPLACEMENT EQUIPMENT FOR MODEL YEAR 1975 THROUGH 1980 BENTLEY AND ROLLS ROYCE SILVER SHADOW, SHADOW II, AND BENTLEY T2 MODEL VEHICLES. THE BRAKE HOSE HAS BEEN INCORRECTLY MANUFACTURED USING A NITRILE RUBBER WHICH IS NOT TOLERANT OF GLYCOL ETHER BASED BRAKE FLUID. 12 VEHICLES IN TOTAL

**Production Dates :** JAN 01, 1975 - DEC 31, 1980

## Description of Defect :

**Description of the Defect :** BENTLEY IS RECALLING CERTAIN SERVICE BRAKE HOSES, PART NUMBER RH14071, SOLD FOR USE AS REPLACEMENT EQUIPMENT FOR MODEL YEAR 1975 THROUGH 1980 BENTLEY AND ROLLS ROYCE SILVER SHADOW, SHADOW II, AND BENTLEY T2 MODEL VEHICLES. THE BRAKE HOSE HAS BEEN INCORRECTLY MANUFACTURED USING A NITRILE RUBBER WHICH IS NOT TOLERANT OF GLYCOL ETHER BASED BRAKE FLUID.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** THIS COULD LEAD TO HOSE FAILURE WHICH WOULD RESULT IN PARTIAL BRAKE FAILURE, INCREASING THE RISK OF A CRASH.

**Description of the Cause :** NR

Identification of Any Warning NR  
that can Occur :

## Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

NR

## Description of Remedy :

Description of Remedy Program : BENTLEY WILL NOTIFY OWNERS AND DEALERS WILL REPLACE THE HOSE FREE OF CHARGE. THE SAFETY RECALL BEGAN ON NOVEMBER 3, 2010. OWNERS MAY CONTACT BENTLEY AT 1-617-488-8500.

How Remedy Component Differs NR  
from Recalled Component :

Identify How/When Recall Condition NR  
was Corrected in Production :

## Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : OCT 30, 2010 - NR

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported