

GM CUSTOMER CARE AND AFTERSALES

DCS2451

URGENT - DISTRIBUTE IMMEDIATELY

Date: August 5, 2010

Subject: 10018C – Safety Recall – Revised
Accelerator Pedal Sticking
Revised Service Procedure, Parts Information, and
Claims
Information Sections

Models: 2009-2010 Pontiac Vibe

To: All GM Dealers (except Saturn and HUMMER)

Attention: General Manager, Service Manager, Parts Manager,
New Car Vehicle Manager, Used Car Vehicle Manager,
and
Warranty Administrator

The Service Procedure, Step 6.3, has been revised to remove the requirement to call the Technical Assistance Center if the clearance between the stopper and housing is greater than 2.70 mm. If the clearance is greater than 2.70 mm, dealers are to replace the pedal. The part number for the pedal has been added to the Parts Information section and a new labor code has been added. Step 12 in the Service Procedure has also been revised to remove programming instructions that are no longer applicable. Please discard all copies of bulletin 10018B, issued February 2010.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.