

GM CUSTOMER CARE AND AFTERSALES

DCS2463

URGENT - DISTRIBUTE IMMEDIATELY

Date: September 14, 2010

Subject: 10038B – Safety Recall
Potential Floor Mat Interference with the Accelerator Pedal
Revised Service Procedure

Models: 2009-10 Pontiac Vibe

To: All GM Dealers (except Saturn and HUMMER)

Attention: General Manager, Service Manager, Parts Manager,
New Car Vehicle Manager, Used Car Vehicle Manager,
and
Warranty Administrator

The Service Procedure section in bulletin 10038B has been revised to clarify that only the Pontiac Vibe All-Weather Floor Mats require replacement. All standard (carpeted) or aftermarket mats are to be reinstalled after this recall has been completed. The revisions can be found in the All Weather Floor Mat Inspection procedure (Step 1, second bullet) and in the Reinstall the Accelerator Pedal Assembly procedure (Step 6).

Please discard all copies of bulletin 10038A, issued July 2010.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.