

**GM CUSTOMER CARE AND AFTERSALES**

**DCS2413**

**URGENT - DISTRIBUTE IMMEDIATELY**

**Date:** June 2, 2010

**Subject:** 10023B – Safety Recall  
Loss of Power Steering Assist – Replace Electric Power  
Steering Motor  
Revised Parts Information and Service Procedure  
Sections

**Models:** 2005-10 Chevrolet Cobalt; 2005 Pontiac Pursuit; 2005-  
06  
Pontiac G4; 2006 Pontiac G5 Pursuit; 2007-10 Pontiac  
G5  
Equipped with Electric Power Steering

**To:** All GM Dealers

**Attention:** General Manager, Service Manager, Parts Manager,  
New Car Vehicle Manager, and Warranty Administrator

The Parts Information and Service Procedure sections in bulletin 10023B have been revised. Technicians are to review the revised information immediately.

Please discard all copies of bulletin 10023A, issued March 2010.

**END OF MESSAGE**

**GM CUSTOMER CARE AND AFTERSALES**

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.