

GM CUSTOMER CARE AND AFTERSALES

DCS2466

URGENT - DISTRIBUTE IMMEDIATELY

Date: September 16, 2010

Subject: 10023D – Safety Recall
Loss of Power Steering Assist – Replace Electric Power
Steering Motor
Revised Parts Information, Service Procedure, and
Claim
Information Sections

Models: 2005-2010 Chevrolet Cobalt, 2005-2006 Pontiac G4,
2007-2010 Pontiac G5 Equipped with Electric Power
Steering

To: All GM Dealers (except Saturn and HUMMER)

Attention: General Manager, Service Manager, Parts Manager,
New Car Vehicle Manager, Used Car Vehicle Manager,
and
Warranty Administrator

The Parts Information, Service Procedure, and Claim Information sections in bulletin 10023D have been revised. Dealers are to no longer use Loctite. All reference to the use of Loctite has been removed. Additional motor kit part numbers have also been added to the Parts Information table.

Please discard all copies of bulletin 10023C, issued June 2010.

END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.